



Renault Captur: L781PJ

Vinnumber:	VF1RJ800767688965	Versionname:	Captur 1.0 TCE 67kW Business Zen
First Registrationdate:	7/07/2021	Fiscalpower:	
Expertise Mileage:	122866	Power Kw:	67
Bodytype:		Body colour	Blanc Nacré
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Petrol	Parking lot	1134
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	1	Rear parking sensors
GPS		Hook
Manual climate control		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 60 / 17 / 96 / H / Aluminium	4,2 mm	Goodyear	Summer
	Right	215 / 60 / 17 / 96 / H / Aluminium	4,1 mm	Goodyear	Summer
Rear	Left	215 / 60 / 17 / 96 / H / Aluminium	4,0 mm	Goodyear	Summer
	Right	215 / 60 / 17 / 96 / H / Aluminium	3,8 mm	Goodyear	Summer

Assistance equipment

Number of charging cables (rapid charge)	0
--	----------

Service, Maintenance, Execute



Ignition key, Missing, Replace

No pictures to display

Floor mat(s), Worn, Replace



Interior, Dirty, Chemical cleaning



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Outer door handle RL, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Bumper corner RR, Stone chip(s), Repair and paint (complete)



Bumper R, Dent(s), Replace



Bumper corner RL, Stone chip(s), Repair and paint (complete)



Bodywork, Chemical polution, Polish



Kenteken	L781PJ
Merk Model	Renault Captur 1.0 TCE 67kW Business Zen
Brandstofsoort	Benzine
Datum deel1	07-07-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
11-12-25	104.689	Reparatie band(en)
13-06-25	89.188	APK
13-06-25	89.188	Bougie
13-06-25	89.188	Luchtfilterhuis
13-06-25	89.188	Onderhoudsbeurt
13-06-25	89.188	Remblokken voorzijde
13-06-25	89.188	Vervanging band
27-11-24	69.928	Accu
27-11-24	69.928	Ruitenwisherblad(en) voorzijde
27-11-24	69.928	Sleutelbatterij
27-11-24	69.928	Uitlaat temperatuur sensor
04-10-24	64.238	Bougie
04-10-24	64.238	Onderhoudsbeurt
04-10-24	64.238	Remvloeistof
04-10-24	64.238	Ruitenwisherblad(en) voorzijde
04-10-23	34.059	Onderhoudsbeurt
30-05-23	28.763	Onderhoudsbeurt
12-01-23	23.153	Vervanging band
07-07-22	15.744	Onderhoudsbeurt