



Opel Corsa: 2ASU636

Vinnumber:	VXKUPHNKSM4209720	Versionname:	
First Registrationdate:	2/07/2021	Fiscalpower:	
Expertise Mileage:	102802	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1310
Fueltype:	Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Tyres

195/55/16/92 H				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				195/55 R 16 92 H
Tyre size FR				195/55 R 16 92 H
Tyre size RL				195/55 R 16 92 H
Tyre size RR				195/55 R 16 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1123,86
Ignition key, Missing, Replace	280,06



Interior, Not original part, Replace	1,00
--------------------------------------	------



Bonnet, Chemical polution, Repair and paint (complete)	0,00
--	------



Headlight L, Scratch(es), Repair/replace (lump sum)	50,00
---	-------



Door RL, Dent(s), Acceptable	0,00
------------------------------	------



Alloy rim RL, Scratch(es), Repair and paint (complete)	133,03
--	--------



Wing RL, Repaired, Acceptable	0,00
-------------------------------	------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Bumper R, Scratch(es), Repair and paint (complete)	237,26
--	--------



Rear window, Scratch(es), Polish	77,26
----------------------------------	-------



Tailgate / Boot, Scratch(es), Acceptable	0,00
--	------



Door FR, Chemical polution, Polish

0,00



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

345,25



Alloy rim RR, Scratch(es), Acceptable

0,00



Roof, Chemical polution, Repair and paint (complete)

0,00

