SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Bas Vaasen

# 2-GDK-520

2-GDK-520 · Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT / · 4 November 2026 · Zaventem Brussel

## Specifications

| | |
|---|---|
| License Plate Number | 2-GDK-520 |
| Manufacturer | TOYOTA |
| Model | Corolla Cross |
| Model Versions | Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT / |
| Body Type | 5 door hatchback |
| Color | Blue |
| Paint Type | Metallic |
| Production Year | 2024 |
| KW | 103 |
| Fuel Type | Hybrid Gasoline |

| | |
|---|---|
| VIN | JTNADADB50J024276 |
| Cylinder Capacity | 1.798 cm3 |
| Transmission Type | Automatisch geschakelde Transmissie |
| First Admission | 05-11-2024 |
| First Registration | 05-11-2024 |
| Odometer | 47.693 Km |
| Numer Of Keys | 2 |
| Interior | Black – Cloth |
| Number Headrests | 5 |

## Images






























UNIROYAL

UNIROYAL


## Accessories

| | |
|---|---|
| ABS | Cruise control |
| Airbags | Electric rear windows |
| Alloy wheels | Electric windows front |
| ASR | Electrically adjustable exterior mirrors |
| Audio System | Leather steering wheel |
| Automatic air conditioning | Parking sensors |
| Bluetooth car kit | Rear view camera |
| Central door locking | Roller cover / parcel shelf |
| Centre armrest | Steering wheel multifunction |

## Condition

| | | | |
|---|---|---|---|
| Condition exterior | Adequate | Last Maintenance | Unknown |
| Condition interior | Adequate | Previous Repairs | Unknown |
| Dog in the car | | | |

## Tire Specifications

| Tire | Profile | Brand | Width | Aspect Ratio | Radial | Type |
|---|---|---|---|---|---|---|
| Front Left | 3 mm | UniRoyal | 215 mm | 60 mm | 17 inch | All Season |
| Rear Left | 5 mm | UniRoyal | 215 mm | 60 mm | 17 inch | All Season |
| Front Right | 3 mm | UniRoyal | 215 mm | 60 mm | 17 inch | All Season |
| Rear Right | 5 mm | UniRoyal | 215 mm | 60 mm | 17 inch | All Season |
| Spare Tire Type | Homecomer | | | | | |

## Damages




| Damage Part | Damage Type | Notes | Repair Type | Acceptable |
|---|---|---|---|---|
| Interior | Scratch(es) | middenconsole | Plastic Repair | No |




| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| Mirror - Rightside | Small scratch(es) | Acceptable | Yes |




| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| Frontdoor – Left | Door-edge chipped | Acceptable | Yes |




| Damage Part | Damage Type | Notes | Repair Type | Acceptable |
|---|---|---|---|---|
| Overfender | Small scratch(es) | LAS / LAP | Acceptable | Yes |









| Damage Part | Damage Type | Notes | Repair Type | Acceptable |
|---|---|---|---|---|
| Rear | Dent(s) & Scratch(es) | sleepoogkap manco<br>onderpaneel gedeukt<br>onderpaneel gescheurd | Panelbeating & Spray | No |






| Damage Part | Damage Type | Notes | Repair Type | Acceptable |
|---|---|---|---|---|
| Interior | Stains & dirt | tevens hondenharen | Cleaning | No |