



Expertise

Protocol number: 46802129
Order No. / Reference: 26844377
Inspection date: 30 Jul 2026

Manufacturer: Volkswagen

Model: Passat Variant 2.0 TDI SCR DSG Business

VIN: WVGZZCJ3SD046200



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen Passat Variant 2.0 TDI SCR DSG Business	
Vehicle Identification number	WVGZZCJ3SD046200
Mileage (Read)	82,928 km
First registration	9 May 2025
Number of holders	1
Next periodical technical inspection	05/2028
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	grenadillschwarz-met allie (Y9T)
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black-Grey



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	4,600 km
Last service on / at	02/2026 at 57,513 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HJ776359
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / CTH 00036		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,250 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 95V	Summer tyres on Light alloy	Kumho	3mm / 3mm
2)	215/60 R16 95V	Summer tyres on Light alloy	Kumho	3mm / 3mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 95H	Winter tyres on Light alloy	Continental	6mm / 6mm
2)	215/60 R16 95H	Winter tyres on Light alloy	Continental	6mm / 6mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 02/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment



Standard equipment

- Turning brake function and evasive steering support
- Airbag for driver and front passenger (with front passenger airbag deactivation, including driver's side knee airbag)
- Ambient lighting
- App-Connect including App-Connect Wireless for Apple CarPlay and Android Auto
- Exterior mirror housings in body color
- Hill start assist
- Vehicle tool kit
- Car2X
- Ceramique headliner
- decorative inlays
- Digital Cockpit Pro, multicolor (various info profiles selectable)
- Electronic differential lock XDS
- Electronic stability program and electromechanical brake booster
- Windscreen made of laminated safety glass, heat-insulating
- Luggage compartment floor adjustable to 2 heights (for a flat loading surface)
- Rear window heated
- rear window wiper
- Infotainment system with 32 cm (12.9 inch) display
- ISOFIX mounting points (for child seats on the outer rear seats and on the front passenger seat, i-Size compatible)
- Rear headrests (3)
- Front headrests (safety-optimized, longitudinally and height-adjustable)
- Stainless steel loading sill protector
- LED taillights
- Steering wheel: Multifunction steering wheel in leather, with paddle shifters
- Mesh partition
- Emergency call service (valid for 10 years from initial delivery, subject to availability of required mobile networks)
- Upholstery: Microfleece "ArtVelours Eco" (center panels of the front seats and outer rear seats)
- Rain sensor
- Wheels: Light alloy (4) "Venezia" 7J x 16, surface polished (tires 215/60 R 16, optimized for rolling resistance)
- Keyless start system without SAFE locking
- Rear side windows and rear window tinted
- Seats: ergoActive front seats, height-adjustable, with sliding thigh support
- Seats: Front seats with massage function
- Lane Assist and Traffic Jam Assist
- Lane change assistant "Side Assist", parking assistant and exit warning
- "Comfort" telephone interface with inductive charging function
- Illuminated door handle recesses
- Front USB-C ports (2) (2 USB-C charging ports on the rear center console; charging power up to 45 W)
- Distraction and fatigue detection
- Airbags: Front and rear head airbags, front side airbags, center airbag
- Anti-lock braking system (ABS)
- Adaptive Cruise Control (ACC) "Stop&Go"
- Folding and heated exterior mirrors, auto-dimming on the driver's side (with ambient lighting and passenger-side mirror lowering)
- third brake light
- Chrome trim on the side windows
- Roof rails, silver anodized
- Diesel particulate filter and SCR catalyst
- Tachometer
- Entry/warning lights in LED technology in the front doors
- Electronic parking brake including auto-hold function
- Electric windows, front and rear
- High beam assistant "Light Assist"
- Pedestrian detection
- Extendable and removable luggage compartment cover
- Speed limiter with predictive control
- Transmission: 7-speed DSG (7-speed dual-clutch transmission DSG)
- Rear spoiler in car color
- Interior mirror automatically dimming
- Child lock
- Air conditioning "Air Care Climatronic" (with active combination filter, rear controls and 3-zone temperature control)
- Intersection assistant
- LED lights in the front footwell, selectable light color
- LED headlights
- Headlight range control
- Navigation system
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Parking assistant "Park Assist Plus" incl. parking aid
- Proactive occupant protection system
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system (passive)
- Rear View reversing camera
- Rear seat backrest asymmetrically split and foldable (with pass-through option)
- Electromechanical power steering (speed-dependent control)
- Seats: Comfort seats in the front
- Sun visors with illuminated makeup mirrors on driver and passenger side
- Start-stop system (with brake energy recuperation)
- Bumpers in body color, air intake with chrome trim, radiator grille with chrome trim
- Textile floor mats front and rear
- Ambient lighting with logo projection
- First aid kit, warning triangle and high-visibility vest
- Traffic sign recognition



- Electronic immobilizer

- Central locking with remote control

Extra equipment

- Towbar including trailer maneuvering assistant "Trailer Assist" (foldable towbar with electric release - parking assistant "Park Assist Plus" including parking aid)
- Package: Business Premium Package (230V socket in the luggage compartment and 12V socket in the luggage compartment - Adaptive chassis control DCC Pro incl. driving profile selection - Luggage net - Luggage compartment floor adjustable to 2 heights, for a flat loading area, with securing bar - Head-up display - Multifunction steering wheel in leather, heated, with shift paddles - Progressive steering - Heated front seats, seat cushion and backrest separately adjustable)
- Package: Occupant Protection Technology Package (Proactive Occupant Protection System - Tire Pressure Monitoring System)
- Paint finish: Metallic
- Package: "IQ.DRIVE" assistance package ("Travel Assist", "Lane Assist" lane keeping assist and "Emergency Assist" - electric child safety locks for rear doors, operable from the driver's seat - "Area View" surround view including "Rear View" reversing camera)
- Package: Infotainment package "Discover Pro Max" in conjunction with "Business Premium" package (Head-up display - Infotainment system with 38.1 cm (15 inch) display (You can intuitively and conveniently select songs, system settings or vehicle data via touch or voice control) - Navigation system - IDA voice assistant and electronic voice amplification (Start the function with "Hello IDA" and turn the vehicle into an intelligent conversation partner))

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
2	Trim / covers	Boot lid - interior trim - Scratch(es) - Smart repair
3	Mudguard - left side	Mudguard - left side - Scratch(es) - Smart repair
4	Door - front left side	Door - Dent / paintcoat damage - Smart repair
5	Sill - left side	Sill - dent(s) - Smart repair
6	Door - rear left side	Door - Dent / paintcoat damage - Smart repair
7	Roof	Roof rail - left side - Dent / paintcoat damage - Repair and paint
8	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint
9	Vehicle glazing	Windscreen - Broken / torn - repair according to calculation

Wear and tear

No.	Component group	Description
1	Trim / covers	Door trim - rear right side - Scratch(es) - No deduction
2	Trim / covers	Roof lining - Scratch(es) - No deduction
3	Trim / covers	Boot lining - Scratch(es) - No deduction
4	Rear bumper	Rear bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres




Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.





Figure 32: Misc.



Figure 33: Misc.




Damage 1: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 1: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 2: Trim / covers: Boot lid - interior trim - Scratch(es) - Smart repair




Damage 3: Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



Damage 3: Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair




Damage 4: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage 4: Door - front left side: Door - Dent / paintcoat damage - Smart repair




Damage 5: Sill - left side: Sill - dent(s) - Smart repair



Damage 5: Sill - left side: Sill - dent(s) - Smart repair



Damage 6: Door - rear left side: Door - Dent / paintcoat damage - Smart repair




Damage 6: Door - rear left side: Door - Dent / paintcoat damage - Smart repair



Damage 7: Roof: Roof rail - left side - Dent / paintcoat damage - Repair and paint




Damage 7: Roof: Roof rail - left side - Dent / paintcoat damage - Repair and paint



Damage 7: Roof: Roof rail - left side - Dent / paintcoat damage - Repair and paint



Damage 8: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 8: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 8: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 9: Vehicle glazing: Windscreen - Broken / torn - repair according to calculation



Damage 9: Vehicle glazing: Windscreen - Broken / torn - repair according to calculation