



PEUGEOT 3008: GP-733-RD

Vinnumber:	VF3MCYHZUPS069770	Versionname:	PEUGEOT 3008 BlueHDi 130 S&S EAT8 Allure Pack VP [5P] bva 8-130CH-7cv (SUV)
First Registrationdate:	20/06/2023	Fiscalpower:	
Expertise Mileage:	51874	Power Kw:	96
Bodytype:	SUV	Body colour:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Dark Grey
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	Lining Other
Type of climate control	Autom climate control		Lining Leather

Tyres

225/55/18/102 V				
Summer tyres:	Fr.L.	Michelin: 85%	Fr.R.	Michelin: 85%
	Re.L.	Michelin: 55%	Re.R.	Michelin: 65%
Tyre profile depth FL				2.6
Tyre profile depth FR				2.5
Tyre profile depth RL				4.6
Tyre profile depth RR				4.1
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Seat cover RR, Stain, Cleaning			



Backrest cover RR, Stain, Cleaning



Tyre FL, Out of tolerance, Replace



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RL bitone/polychrome, Scratch(es), Acceptable



Tyre FR, Out of tolerance, Replace



Wing RL, Scratch(es), Polish



Windscreen, Crack, Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Wing trim RR, Missing, Replace



Door RR, Scratch(es), Polish



Door FR, Scratch(es), Polish



Side repeater R, Scratch(es), Replace



Wing trim FR, Missing, Replace



Boot lid covering R, Scratch(es), Replace



Rear bulkhead lining, Scratch(es), Replace



Internal boot lining R, Scratch(es), Replace



Bumper corner RL, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Polish



Historique Maintenance

Immatriculation: **GP-733-RD**Date de 1ère immatriculation: **20/06/2023**Modèle: **Peugeot 3008 BlueHDi 130 S&S EAT8 Allure Pack VP [5P] bva 8-130CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
08/01/2026	46.528	STELLANTIS &YOU FRANCE SAS	TELECHARGEMENT CALCULATEUR
	0		REVISION
23/07/2025	37.708	STELLANTIS &YOU FRANCE SAS	FILTRE CLIM RPLT
	0		LIQUIDE DE FREIN
	0		ADBLUE
	0		BALAI ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		REVISION
02/08/2024	20.465	STELLANTIS &YOU FRANCE SAS	ADBLUE
	0		BALAI ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		REVISION