


Vehicle details

VIN	5YJ3E7EA3 MF897203	Brand	TESLA	Maintenance date	-
Licence Plate	[REDACTED]	Model	Model 3 Standard Range Plus RWD 4d	Maintenance mileage	-
Registration date	29/06/2021	Year	2021	Exterior Color	Black Metallic
Odometer	149 665 km	Engine size	-	interior Color	Black
Fuel	Electric	Body Type	Saloon / Hatchback	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	-		

Inspection Details

Inspection date	02/07/2026	Inspection loc.	
-----------------	------------	-----------------	--



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Vehicle charger	✓
Wireless charger	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres







Hankook 235/40/19 Summer 3.0 mm

Hankook 235/40/19 Summer 3.0 mm

Hankook 235/40/19 Summer 3.0 mm

Hankook 235/40/19 Summer 3.0 mm

Exterior

<p>1</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Wing	Position	Front left	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	<p>2</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Back	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair
Part	Wing																						
Position	Front left																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
Part	Bumper																						
Position	Back																						
Damages	Scratched																						
Severity	Length (cm) > 10																						
Repair mode	Repair																						
<p>3</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Alloy wheel 19"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 19"	Position	Front right	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair	<p>4</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Bonnet	Position	-	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair
Part	Alloy wheel 19"																						
Position	Front right																						
Damages	Scratched																						
Severity	-																						
Repair mode	Lumpsum repair																						
Part	Bonnet																						
Position	-																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						