



VOLVO XC40: GE-073-RB

Vinnumber:	YV1XZBWVFN2750695	Versionname:	VOLVO XC40 Recharge T4 211 DCT7 Inscription Busi
First Registrationdate:	14/02/2022	Fiscalpower:	VP [5P] bva 7-211CH-7cv (SUV)
Expertise Mileage:	116616	Power Kw:	155
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Sun Roof electric	
GPS big screen color		Panoramic roof	
GPS storage		Central consol F	
Windows electric F	HD	Luggage cover	
Windows electric R		Headlights Xenon/LED/Laser	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Rear view camera	
Type of climate control	Autom climate control	Seat cover lining	Lining Other

Tyres

	235/55/18/100 V			
Summer tyres:	Fr.L.	Michelin: 60%	Fr.R.	Michelin: 60%
	Re.L.	Michelin: 45%	Re.R.	Michelin: 45%
Tyre profile depth FL				4.3
Tyre profile depth FR				4.4
Tyre profile depth RL				5.4
Tyre profile depth RR				5.4
Tyre size FL				235/55 R 18 100 V
Tyre size FR				235/55 R 18 100 V
Tyre size RL				235/55 R 18 100 V
Tyre size RR				235/55 R 18 100 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Interior, Stain, Cleaning



Inner door sill FR, Scratch(es), Paint



Door FL, Dent(s), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Polish



Bumper F, Scratch(es), Paint



Bumper moulding F, Scratch(es), Replace



Bumper spoiler F, Scratch(es), Paint



Bonnet, Dent(s), Repair and paint (complete)



Wing trim FR, Scratch(es), Replace



Wing FR, Scratch(es), Paint



Door RR, Scratch(es), Paint



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Door trim FR, Scratch(es), Replace



Boot lid covering R, Scratch(es), Replace



Rubber seal for boot lid, Tear, Replace



Bumper R, Deformed / Strained, Repair and paint (complete)



Bumper spoiler Rear, Scratch(es), Paint



Luggage compartment cover, Deformed / Strained, Replace



Historique Maintenance

Immatriculation: **GE-073-RB** Date de 1ère immatriculation: **14/02/2022**

Modèle: **Volvo XC40 Recharge T4 211 DCT7 Inscription Busi VP [5P] bva 7-211CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
10/06/2026	116.608	LARSON MARNE LA VALLEE BY AUTOSPHERE	MODULE ELEC RPLT
			HUILE BV RPLT
			LIQUIDE DE FREIN
			REVISION ET CLIM ET AIR ET BOUGIES
08/01/2025	95.149	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS ETE
09/12/2024	92.019	ACTIV'AUTO	PLAQUETTES AR RPLT
			REVISION ET CLIM
			PLAQUETTES AV RPLT
15/03/2024	67.508	ACTIV'AUTO	HUILE BV RPLT
			BALAIS ESSUIE GLACE AV AR
			LIQUIDE DE FREIN
			REVISION ET CLIM ET AIR ET BOUGIES
31/07/2023	45.491	ACTIV'AUTO	REMPLACEMENT PNEUS ETE
20/12/2022	25.595	ACTIV'AUTO	REVISION ET CLIM