SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-FJS-654

2-FJS-654 · COMBI L2H12.0dCi 150 DCT N-CONNECTA · 20 October 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FJS-654
Manufacturer	NISSAN
Model	Primastar
Model Versions	COMBI L2H12.0dCi 150 DCT N-CONNECTA
Body Type	VAN
Color	Black
Paint Type	Metallic
Production Year	2024
KW	110

Fuel Type	Diesel
VIN	VNVJ4000473210841
Cylinder Capacity	1.997 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	24-05-2024
Odometer	61.405 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	9

Images






























Accessories

- ABS
- Airbags
- Audio System
- Bluetooth car kit
- Central door locking
- Centre armrest
- Cruise control
- Electric windows front
- Electrically adjustable exterior mirrors
- Fog lights
- Leather steering wheel
- Manual air conditioning
- Navigation system
- Rear parking sensors
- Rear view camera
- Steering wheel multifunction
- Tow bar

Condition

Condition exterior	Adequate
Condition interior	Adequate
Last Maintenance	06-05-2026
Last maintenance odometer	42.477
Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 mm	Goodyear	215 mm	65 mm	16 inch	Summer
Rear Left	6 mm	Goodyear	215 mm	65 mm	16 inch	Summer
Front Right	4 mm	Goodyear	215 mm	65 mm	16 inch	Summer
Rear Right	6 mm	Goodyear	215 mm	65 mm	16 inch	Summer
Spare Tire Type	Fully Fledged					
Spare Tire Profile	8 mm					

Damages





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Mirror - leftside	Signallight broken	Replace	No





Damage Part	Damage Type	Repair Type	Acceptable
Mirror - leftside	Small scratch(es)	Repair	No





Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes





Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Scratch(es)	B stijl	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Scratch(es)	Polish	No





Damage Part	Damage Type	Repair Type	Acceptable
Windscreen – Rear	Scratch(es)	Replace	No





Damage Part	Damage Type	Repair Type	Acceptable
Roof	Birddropping stained	Spotrepair	No





Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No



Damage Part	Damage Type	Repair Type	Acceptable
Trunkshelf	Missing	Replace	No