

2-DMC-825

2-DMC-825 · Titanium 1.0i Ecoboost 100pk 74kw · 30 June 2026 · Zaventem (BE)

Specifications

| | | | |
|----------------------|-----------------------------------|-------------------|-----------------------------------|
| License Plate Number | 2-DMC-825 | Fuel Type | Gasoline |
| Manufacturer | FORD | VIN | WF0JXXGAHJPE36625 |
| Model | Fiesta | Cylinder Capacity | 999 ^{cm³} |
| Model Versions | Titanium 1.0i Ecoboost 100pk 74kw | Transmission Type | Handmatig geschakelde transmissie |
| Body Type | 5 door hatchback | First Admission | 24-04-2023 |
| Color | Grey | Odometer | 70.117 ^{km} |
| Paint Type | Metallic | Numer Of Keys | 2 |
| Production Year | 2023 | Interior | Black |
| KW | 74 | Number Headrests | 5 |

Images





Accessories

ABS

Airbags

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Leather steering wheel

Rear parking sensors

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Windscreen - Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs

Unknown

Tire Specifications

| Tire | Profile | Brand | Width | Aspect Ratio | Radial | Type |
|-----------------|-----------------|--------------|-------------------|---------------------|--------------------|-------------|
| Front Left | 5 ^{mm} | Hankook | 195 ^{mm} | 60 ^{mm} | 15 ^{inch} | All Season |
| Rear Left | 3 ^{mm} | Continental | 195 ^{mm} | 60 ^{mm} | 15 ^{inch} | All Season |
| Front Right | 5 ^{mm} | Hankook | 195 ^{mm} | 60 ^{mm} | 15 ^{inch} | All Season |
| Rear Right | 3 ^{mm} | Continental | 195 ^{mm} | 60 ^{mm} | 15 ^{inch} | All Season |
| Spare Tire Type | Compressor | | | | | |

Damages



Damage Part

Interior



Damage Type

Scratch(es)

Notes

Pookknop

Repair Type

Replace

Acceptable

No



Damage Part

Fender - Rear Left



Damage Type

Small dent(s)

Repair Type

Restyle

Acceptable

No



Damage Part

Frontdoor - Left



Damage Type

Door-edge chipped

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Wheelcover - Left Front



Damage Type

Damaged

Repair Type Acceptable

Replace No



Damage Part

Hood



Damage Type

Stonechipping

Repair Type Acceptable

Acceptable Yes



Damage Part

Fender - Front Left



Damage Type

Damaged

Repair Type Acceptable

Spray No



Damage Part

Wheelcover - Right Front



Damage Type

Damaged

Repair Type Acceptable

Replace No



Damage Part

Wheelcover - Right Rear



Damage Type

Damaged

Repair Type Acceptable

Replace No



Damage Part

Interior



Damage Type

Stains & dirt

Repair Type Acceptable

Cleaning No