



Opel Corsa: T841DP

Vinnnumber:	VXKUHZKXZP4108426	Versionname:	Corsa-E 3 fase lader 100kW / 50kWh Edition
First Registrationdate:	31/05/2023	Fiscalpower:	
Expertise Mileage:	68675	Power Kw:	100
Bodytype:		Body colour:	Crystal Silver metallic
Gearbox:	Automatic	Paint type:	Metallic
Transmission:		Type of rims (mounted):	Steel
Fueltype:	Electric	Parking lot:	404
Number of seats:	5		
Type of rims (mounted):	Steel		
Maintenance needed:	No		

Options

Number of keys total	2
Autom climate control	
Radio multimedia	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 55 / 16 / 91 / H / Steel	3,0 mm	Goodyear	All season
	Right	195 / 55 / 16 / 91 / H / Steel	3,0 mm	Goodyear	All season
Rear	Left	195 / 55 / 16 / 91 / H / Steel	4,2 mm	Goodyear	All season
	Right	195 / 55 / 16 / 91 / H / Steel	3,0 mm	Goodyear	All season

Assistance equipment

Number of charging cables (rapid charge)	1
Seat cover FR, Stain, Cleaning	



Outside rear-view mirror housing L, Scratch(es), Replace and paint



Wing RL, Dent(s), Repair and paint (complete)



Bumper F, Dent(s), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Roof, Chemical polution, Polish



Kenteken	T841DP
Merk Model	Opel Corsa-E 3 fase lader 100kW / 50kWh Edition
Brandstofsoort	Elektrisch
Datum deel1	31-05-23

Datum reparatie	Kilometerstand	Reparatie omschrijving
30-09-25	48.239	Onderhoudsbeurt
30-09-25	48.239	Remvloeistof
01-05-25	40.052	Reparatie band(en)
23-09-24	22.898	Reparatie band(en)
11-09-24	21.736	Stellantis eerste EV controle