



FORD MONDEO CLIPPER: [Redacted]

Vinnnumber:	WF0FXXWPCHLT32860	Versionname:	2.0 HEV 140kW Aut. Titanium HEV
First Registrationdate:	19/01/2021	Fiscalpower:	
Expertise Mileage:	118468	Power Kw:	140
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2413
Fueltype:	Hybrid Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	Tow bar removable
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Tyres

215/55/17/92 H				
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Tyre profile depth FL	5.0
Tyre profile depth FR	5.0
Tyre profile depth RL	5.0
Tyre profile depth RR	5.0
Tyre size FL	215/55 R 17 92 H
Tyre size FR	215/55 R 17 92 H
Tyre size RL	215/55 R 17 92 H
Tyre size RR	215/55 R 17 92 H
Tyre type FL	Summer
Tyre type FR	Summer
Tyre type RL	Summer
Tyre type RR	Summer
Tyre make FL	2480
Tyre make FR	2480
Tyre make RL	259
Tyre make RR	259

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	546,30
-------------------	--------

Door panel RL, Scratch(es), Acceptable	0,00
--	------



Seat cover FL, Hole, Smart repair 116,69



Bumper F, Dent(s), Acceptable 0,00



Bonnet, Dent(s), Acceptable 0,00



Bumper F, Scratch(es), Acceptable 0,00



Wing FL, Dent(s), Acceptable 0,00



Step L, Dent(s) and scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Repair and paint (complete) 296,58



Tailgate / Boot, Repaired, Acceptable 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete) 133,03



Alloy rim RR, Scratch(es), Acceptable

0,00



Door RR, Dent(s), Acceptable

0,00

