



Skoda Scala (UKL): 1YVZ818

Vinnumber:	TMBEH6NW7M3066094	Versionname:	Scala Ambition 1.0TGi 90pk/cv 5p
First Registrationdate:	7/01/2021	Fiscalpower:	
Expertise Mileage:	24402	Power Kw:	66
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	in 13300 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres


	205/55/16/91 V			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 16 91 V
Tyre size FR				205/55 R 16 91 V
Tyre size RL				205/55 R 16 91 V
Tyre size RR				205/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Interior, Dirty, Forfeit





Door panel RL, Scratch(es), Replace




Door panel RR, Scratch(es), Replace



Roof liner, Scratch(es), Replace





Dashboard, Scratch(es), Acceptable



Bonnet, Dent(s), Paintless dent repair



Bumper F, Scratch(es), Spot repair



Central pillar L, Dent(s) and scratch(es), Spot repair



Alloy rim RL, Scratch(es), Acceptable



Outer sill L, Deformed / Strained, Repair and paint (complete)



Wing RL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Bumper moulding R, Scratch(es), Replace



Central pillar R, Dent(s), Acceptable



Alloy rim RR, Scratch(es), Acceptable



Kenteken	1YVZ818
Merk Model	Skoda Scala Ambition 1.0TGi 90pk/cv 5p
Brandstofsoort	CNG
Datum deel1	1/7/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
2/11/26	26,021	Inspectie met olie vervanging (vast in	Uitvoeren
2/11/26	26,021	klein materiaal	
2/11/26	26,021	luchtfilter interieur	Vervangen
3/6/25	18,735	bougie	Vervangen
3/6/25	18,735	klein materiaal	
3/6/25	18,735	koelwatervloeistof	Bijvullen/-laden
3/6/25	18,735	remvloeistof	Bijvullen/-laden
3/6/25	18,735	ruitenwisserrubber vooraan	Vervangen
3/6/25	18,735	ruitenwisservloeistof	Bijvullen/-laden
3/6/25	18,735	Tussentijds onderhoud (vast interval)	Uitvoeren
2/15/24	12,950	Inspectie met olie vervanging (vast in	Uitvoeren
2/15/24	12,950	klein materiaal	
2/15/24	12,950	koelwatervloeistof	Bijvullen/-laden
2/15/24	12,950	luchtfilter interieur	Vervangen
2/15/24	12,950	ruitenwisservloeistof	Bijvullen/-laden
2/22/23	7,878	klein materiaal	Uitvoeren
2/22/23	7,878	luchtfilter interieur	Vervangen
2/22/23	7,878	remvloeistof	Vervangen
2/22/23	7,878	ruitenwisservloeistof	Bijvullen/-laden
2/22/23	7,878	Tussentijds onderhoud (vast interval)	Uitvoeren
2/17/22	3,652	Inspectie met olie vervanging (vast in	Uitvoeren
2/17/22	3,652	klein materiaal	Uitvoeren
2/17/22	3,652	ruitenwisservloeistof	Bijvullen/-laden