



Peugeot 208 (UKL): 2CXA447

Vinnumber:	VR3UPHNSSN5903986	Versionname:	208 GT 1.2 PureTech S&S 130pk/cv 5p EAT8
First Registrationdate:	2/01/2023	Fiscalpower:	
Expertise Mileage:	68958	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	in 12400 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/45/17/88 V			
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				205/45 R 17 88 V
Tyre size FR				205/45 R 17 88 V
Tyre size RL				205/45 R 17 88 V
Tyre size RR				205/45 R 17 88 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Engine insulation, Tear, Replace			



Grille, Broken, Replace



Bumper F, Scratch(es), Repair and paint (complete)



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s), Acceptable



Door FL, Dent(s), Paintless dent repair




Boot carpet, Damaged, Replace



Bumper moulding R, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Kenteken	2CXA447
Merk Model	Peugeot 208 GT 1.2 PureTech S&S 130pk/cv 5p EAT8
Brandstofsoort	Benzine
Datum deel1	1/2/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
12/2/25	60,123	60000 km	Uitvoeren
12/2/25	60,123	klein materiaal	
12/2/25	60,123	remvloeistof	Vervangen
10/18/24	41,594	klein materiaal	N.v.t.
10/18/24	41,594	onderhoud 2e jaar	Uitvoeren
10/18/24	41,594	ruitwisserrubber achter	Vervangen
10/18/24	41,594	ruitwisserrubber vooraan	Vervangen
11/28/23	22,637	klein materiaal	N.v.t.
11/28/23	22,637	onderhoud 1e jaar	Uitvoeren