



Peugeot 3008 (UKL): 2CFV455

Vinnumber:	VF3M4DGZUNS088811	Versionname:	3008 Allure Pack 1.6 PureTech Hybrid 225pk/cv 5p e-EAT8
First Registrationdate:	7/07/2022	Fiscalpower:	
Expertise Mileage:	94230	Power Kw:	133
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Hybrid Petrol		
Maintenance	OK		
Maintenance	25400 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/55/18/102 V			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	0		

Seat cover FL, Damaged, Acceptable



Bumper F, Scratch(es), Spot repair



Bumper spoiler F, Scratch(es), Replace



Wing trim FL, Scratch(es), Replace



Door FL, Dent(s) and scratch(es), Acceptable



Charging cable (fast), Missing, Check



Boot lid covering R, Scratch(es), Replace



Door RR, Scratch(es), Acceptable



Roof, Dent(s), Acceptable



Kenteken	2CFV455
Merk Model	Peugeot 3008 Allure Pack 1.6 PureTech Hybrid 225pk/cv 5p e-EAT8
Brandstofsoort	Benzine
Datum deel1	7/7/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/1/26	89,721	90000 km	Uitvoeren
6/1/26	89,721	halogeenlamp	Vervangen
6/1/26	89,721	remvloeistof	Vervangen
5/4/26	88,258	diagnose	Uitvoeren
5/4/26	88,258	klepdeksel	Vervangen
6/30/25	71,557	oliezeef	Vervangen
6/30/25	71,557	onderhoud 12 maand	Uitvoeren
6/30/25	71,557	ruitenswisserrubber vooraan	Vervangen
6/28/24	47,213	bougie	Vervangen
6/28/24	47,213	luchtfILTER	Vervangen
6/28/24	47,213	luchtfILTER interieur	Vervangen
6/28/24	47,213	oliezeef	Vervangen
6/28/24	47,213	onderhoud 12 maand	Uitvoeren
6/28/24	47,213	remvloeistof	Vervangen
6/28/24	47,213	ruitenswisserrubber vooraan	Vervangen
7/4/23	22,373	30000 km	Uitvoeren
7/4/23	22,373	oliezeef	Vervangen
7/4/23	22,373	ruitenswisserrubber vooraan	Vervangen