



Ford Mustang: L088NX

Vinnumber:	WF0TK1E74MMA16090	Versionname:	Mustang Mach-E 210kW/ 98,8kWh Extended RWD automaat
First Registrationdate:	5/07/2021	Fiscalpower:	
Expertise Mileage:	135030	Power Kw:	210
Bodytype:		Body colour	Premium Metaallak: Lucid Red
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	679
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	1	Lining leather
GPS		Rear parking sensors
Autom climate control		Tow bar removable
Radio multimedia		Hook
		Rear view camera

Tyres


Location	Position	Measures	Depth	Make	Type
Front	Left	228 / 60 / 18 / 104 / V / Aluminium	3,8 mm	Continental	Summer
	Right	228 / 60 / 18 / 104 / V / Aluminium	4,2 mm	Continental	Summer
Rear	Left	228 / 60 / 18 / 104 / V / Aluminium	5,0 mm	Continental	Summer
	Right	228 / 60 / 18 / 104 / V / Aluminium	4,5 mm	Continental	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
Ignition key, Missing, Replace	

No pictures to display

Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Dent(s), Paintless dent repair





Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Roof pillar L, Scratch(es), Repair and paint (complete)



Bonnet, Scratch(es), Polish



Bumper F, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Polish



Door FR, Dent(s) and scratch(es), Repair and paint (complete)





Mirror side repeater R, Scratch(es), Replace



Door RR, Dent(s) and scratch(es), Repair and paint (complete)




Tailgate / Boot, Stone chip(s), Repair and paint (complete)



Bumper corner RL, Scratch(es), Repair and paint (complete)



Roof, Dent(s) and scratch(es), Repair and paint (complete)



Kenteken	L088NX
Merk Model	Ford Mustang Mach-E 216kW/ 98,8kWh Extended RWD automaat
Brandstofsoort	Elektrisch
Datum deel1	05-07-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
02-06-25	106.296	APK
02-06-25	106.296	Onderhoudsbeurt
02-06-25	106.296	Ruitenwisserblad(en) voorzijde