



Peugeot 2008 (UKL): 2AMJ693

Vinnumber:	VR3USHNKKMJ684654	Versionname:	2008 Allure 1.2 Puretech S&S 100pk/cv 5p
First Registrationdate:	12/05/2021	Fiscalpower:	
Expertise Mileage:	87504	Power Kw:	74
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	NOT OK		
Maintenance	met 1100 km overschreden		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	215/60/17/96 H			
Winter tyres:	Fr.L.	Vredestein: 3 mm	Fr.R.	Vredestein: 3 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/60 R 17 96 H
Tyre size FR				215/60 R 17 96 H
Tyre size RL				215/60 R 17 96 H
Tyre size RR				215/60 R 17 96 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
Service, Maintenance, Check			



Door panel RL, Scratch(es), Acceptable



Bumper F, Scratch(es), Spot repair



Bumper spoiler F, Scratch(es), Acceptable



Windscreen, Stone chip(s), Acceptable



Bonnet, Stone chip(s), Acceptable



Alloy rim RL polished, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable




Bumper moulding R, Scratch(es), Repair and paint (complete)



Bumper trim R, Scratch(es), Smart repair



Alloy rim FR polished, Scratch(es), Acceptable




Wing trim FR, Scratch(es), Smart repair



Outside rear-view mirror housing R, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable



Wing RR, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Acceptable



Kenteken	2AMJ693
Merk Model	Peugeot 2008 Allure 1.2 Puretech S&S 100pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	5/12/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
7/28/25	68,712	60000 km	Uitvoeren
7/28/25	68,712	bougie	Vervangen
7/28/25	68,712	luchtfilter	Vervangen
7/28/25	68,712	luchtfilter interieur	Vervangen
7/28/25	68,712	oliezeef	Vervangen
7/28/25	68,712	remschijven en blokken vooraan	Vervangen
7/28/25	68,712	ruitenswisserrubber vooraan	Vervangen
3/31/25		1 batterij	Vervangen
8/26/24	53,339	onderhoud 3e jaar	Uitvoeren
4/12/23	31,689	oliezeef	Vervangen
4/12/23	31,689	onderhoud 2e jaar	Uitvoeren
4/12/23	31,689	remvloeistof	Vervangen
1/25/23	24,233	ruitenswisservloeistof	Bijvullen/-laden
5/24/22	10,222	oliezeef	Vervangen
5/24/22	10,222	onderhoud 1e jaar	Uitvoeren