MACADAM










Volkswagen Caddy: VRT83H

Vinnumber:	**WV1ZZZSK7PX007969**	Versionname:	**Caddy 1.5 TSI 98kW CNG Maxi (o.v. voor PostNL-Post) klant-spec.**
First Registrationdate:	**6/10/2022**	Fiscalpower:	
Expertise Mileage:	**172279**	Power Kw:	**98**
Bodytype:		Body colour	**Candy white**
Gearbox:	**MAN 6 VIT**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Steel**
Fueltype:	**Gas**	Parking lot	**939**
Number of seats	**2**		
Type of rims (mounted)	**Steel**		
Maintenance needed	**Yes**		

Options

Number of keys total	**2**	Rear parking sensors	
Manual climate control		Sliding door right-side	
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 55 / 17 / 98 / V / Steel	2,5 mm	Continental	All season
	Right	215 / 55 / 17 / 98 / V / Steel	4,5 mm	Continental	All season
Rear	Left	215 / 55 / 17 / 98 / V / Steel	5,5 mm	Continental	All season
	Right	215 / 55 / 17 / 98 / V / Steel	6,0 mm	Continental	All season

Assistance equipment

Service, Maintenance, Execute



Seat cover FL, Tear, Replace




Interior, Dirty, Chemical cleaning





Outer sill L, Dent(s), Repair and paint (complete)




Outside rear-view mirror housing L, Scratch(es), Replace




Wing RL, Dent(s), Repair and paint (complete)





Wheel cover RL, Missing, Replace



Bumper F, Deformed / Strained, Replace








Bonnet, Dent(s), Repair and paint (complete)




Windscreen, Crack, Windscreen repair




Sliding door R, Dent(s), Repair and paint (complete)





Outer sill R, Dent(s), Repair and paint (complete)





Boot door lining L, Hole, Smart repair




Boot door panel RR, Dent(s), Repair and paint (complete)






Bumper R, Deformed / Strained, Replace





Onderhoudshistorie van: WV1ZZZSK7PX007969

ALPHABET

Kenteken	VRT83H
Merk Model	Volkswagen Caddy 1.5 TSI 98kW CNG Maxi (o.v. PostNL-Post) klantspec.
Brandstofsoort	CNG
Datum deel1	10/6/22

Datum reparatie	Kilometerstand	Reparatie omschrijving
9/21/26	165,935	Reparatie band(en)
9/3/26	165,934	Vervanging band
9/3/26	168,563	Vervanging band
7/21/26	159,907	Reparatie band(en)
7/9/26	158,611	Vervanging band
7/7/26	158,191	Vervanging band
5/28/26	153,483	Vervanging band
3/18/26	137,529	Parkeersensor
2/16/26	137,529	Koppeling compleet
2/16/26	137,529	Onderhoudsbeurt
2/16/26	137,529	Parkeersensor
2/16/26	137,529	Remblokken achterzijde
2/16/26	137,529	Remblokken voorzijde
2/16/26	137,529	Vliegwiel
1/30/26	143,677	Vervanging band
9/25/25	130,468	APK
9/25/25	130,468	Gaskabel
9/25/25	130,468	Multiriem inclusief spanner
9/25/25	130,468	Onderhoudsbeurt
9/25/25	130,468	Raambediening schakelaar
9/25/25	130,468	Remschijf + blokken achter
9/25/25	130,468	Ruitenwisserblad(en) voorzijde
9/4/25	127,342	Vervanging band
7/31/25	123,453	Vervanging band
6/12/25	116,315	Onderhoudsbeurt
5/2/25	110,690	Vervanging band
2/25/25	102,091	Bougie
2/25/25	102,091	Luchtfilter
2/25/25	102,091	Onderhoudsbeurt
2/25/25	102,091	Remblokken achterzijde
2/25/25	102,091	Remblokken voorzijde
2/25/25	102,091	Remvloeistof
2/25/25	102,091	Sleutelbatterij
2/19/25	101,367	Vervanging band
1/29/25	98,997	Vervanging band
1/21/25	97,677	Vervanging band
10/16/24	85,109	Onderhoudsbeurt
10/16/24	85,109	Remblokken achterzijde
10/16/24	85,109	Remblokken voorzijde
10/16/24	85,109	Ruitenwisserblad(en) voorzijde

Datum reparatie	Kilometerstand	Reparatie omschrijving
10/16/24	85,109	Vervanging band
9/9/24	79,690	Sleutelbatterij
8/9/24	0	Accu
7/25/24	72,788	Vervanging band
7/8/24	70,742	Onderhoudsbeurt
7/8/24	70,742	Remblokken achterzijde
7/8/24	70,742	Ruitenwisserblad(en) achterzijde
6/25/24	68,766	Vervanging band
4/4/24	58,913	Vervanging band
3/13/24	58,490	Bougie
3/13/24	58,490	Onderhoudsbeurt
3/13/24	58,490	Remschijf + blokken achter
3/13/24	58,490	Remschijf + blokken voor
1/4/24	50,609	Vervanging band
10/2/23	39,901	Onderhoudsbeurt
10/2/23	39,901	Remblokken achterzijde
9/25/23	38,874	Vervanging band
7/7/23	29,544	Remblokken achterzijde
7/7/23	29,544	Remschijf + blokken voor
5/4/23	24,331	Vervanging band
3/13/23	17,643	Onderhoudsbeurt
3/13/23	17,643	Remblokken achterzijde
3/13/23	17,654	Vervanging band
1/25/23	11,654	Vervanging band