APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	RENAULT
Model / version:	CAPTUR
Vin:	VF1RJB00367697131
Plate:	2BBG094
Mileage:	73405
First registration:	17/09/2021
Color:	Zilver grijs

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES
















































VIN INFORMATION

Boîte manuelle	6 rapports	Projecteurs à allumage automatique
Feux arrière à LED	Code équipement EA3	Poignées de portes ton caisse
Matière : alliage	Lettre repère (J)	Diamètre avant 17
Diamètre arrière 17	Largeur avant 7,0	Largeur arrière 7,0
Diamètre avant 17	Diamètre arrière 17	Hauteur avant 60
Hauteur arrière 60	Indice de vitesse avant H	Indice de vitesse arrière H
Largeur avant 215	Largeur arrière 215	Climatisation automatique
Climatisation réfrigérant 1234YF	Accoudoir central avant	Essence
999 cm3	1.00 litre	74 kw
101 ch	Euro 6	Métallisée vernissée
Rétroviseur gauche chauffant	Rétroviseur droit chauffant	Rétroviseur gauche jour/nuit automatique
Rétroviseur droit jour/nuit automatique	Rétroviseurs rabattables électriques	Rétroviseurs peints

Rétroviseur intérieur jour/nuit automatique	Siège avant gauche chauffant	Sièges avant chauffants
Siège avant gauche réglable en hauteur	Garnitures tissu et simili-cuir	Aide au stationnement avant
Aide au stationnement arrière	Caméra arrière de recul	Régulateur et limiteur de vitesse
Verrouillage centralisé à commande à distance	Appel de secours	détecteur de pluie essuie-vitre
Airbag latéraux avant	Airbag rideaux avant	Airbag rideaux arrière
Témoin d'oubli de ceinture avant	Témoin d'oubli de ceinture arrière	Protection piéton
Assistant maintien de la voie	Freinage d'urgence assistée autonome (urbain)	depuis 05.21
carrosserie renforcée 03 (CHC03)	passage automatique des phares longue portée en feux de croisement (PRAHL)	volant en mousse 1 (VLMOU1)
tableau de bord numérique + indicateurs analogiques (MET04)	éclairage intérieur av/ar avec 4 lampes de lecture à LED (ECLHB4)	Eco Mode
Micro Hybrid (HYB01)	gestion de la vitesse et du trafic (AVTSR1)	suspension durcie 1 (TRSEV1)
alarme distance de sécurité (DWGE01)	frein à main électrique (FPASS)	événement commercial EV2GA1
peinture 2 tons (2TON)		

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	6 mm			Summer		?
Front right	6 mm			Summer		?
Rear left	6 mm			Summer		?
Rear right	6 mm			Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Interior	Dirty
3	Door FR	Scratch(es)
4	Door RR	Dent(s)

Total: 3

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
2	Bodywork	Damaged	✓	✗	✗

Total: 1

DAMAGES DETAILS

1 - Interior - Dirty





3 - Door FR - Scratch(es)





4 - Door RR - Dent(s)




2 - Bodywork - Damaged - Renta®







SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

02/11/2026 10:56

