



RENAULT EXPRESS: 9842-MCF

Vinnumber:	VF1RJK00970098969	Versionname:	Confort 1.5 Blue dCi 70 kW (95 cv) furgón derivado de turismo 70kW 4P manual
First Registrationdate:	14/11/2022	Fiscalpower:	
Expertise Mileage:	58104	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Tow bar	
Number keys remote	2	Radio	
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of climate control	Manual climate control		

Tyres

	185/65/15/92 T			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Kumho: 3 mm	Re.R.	Kumho: 3 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				185/65 R 15 92 T
Tyre size FR				185/65 R 15 92 T
Tyre size RL				185/65 R 15 92 T
Tyre size RR				185/65 R 15 92 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				2482
Tyre make RR				2482

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Interior, Dirty, Cleaning



Door panel RL, Scratch(es), Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Boot door panel RL, Scratch(es), Paint



Rear panel, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check

