



Renault Kangoo:

Vinnumber:	VF1WF000867524066	Versionname:	
First Registrationdate:	8/06/2021	Fiscalpower:	
Expertise Mileage:	237040	Power Kw:	
Bodytype:		Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:		Parking lot:	3611
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting Halogen		
Type of GPS:	No GPS		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection

Tyres

195/65/15/95 V				
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				195/65 R 15 95 V
Tyre size FR				195/65 R 15 95 V
Tyre size RL				195/65 R 15 95 V
Tyre size RR				195/65 R 15 95 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	2319,25
Interior, Worn, Acceptable:	0,00





Bumper F, Broken, Replace 361,26



Bonnet, Dent(s), Paintless dent repair 159,11



Wheel cover FL, Scratch(es), Replace 44,82



Wheel arch cover FL, Broken, Replace 114,45



Door FL, Dent(s) and scratch(es), Acceptable 0,00



Wheel cover RL, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)

516,48



Rear light L, Broken, Replace

97,56



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)

397,46



Wheel cover RR, Scratch(es), Acceptable

0,00



Wing RR, Deformed / Strained, Repair and paint (complete)

583,29



Sliding door R, Dent(s) and scratch(es), Acceptable

0,00



Outside rear-view mirror housing R, Scratch(es), Acceptable

0,00



Wheel cover FR, Scratch(es), Replace

44,82



Roof, Dent(s) and scratch(es), Acceptable

0,00

