MACADAM







Mercedes CLA-Klasse (KKL): 2CMR587

Vinnumber:	**W1K5J8GB4PN338674**	Versionname:	**CLA250e Sedan Business Solution 1.3i 218pk/cv 4p 8G-DCT**
First Registrationdate:	**19/09/2022**	Fiscalpower:	
Expertise Mileage:	**46703**	Power Kw:	**118**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Plug-in Hybrid Petrol**		
Maintenance	**OK**		
Maintenance	**ass A1 plus 292 d**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Type of Tow bar	**No Tow bar**
GPS			
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/45/18/91 W**			
	Fr.L.	**Continental: 4 mm**	Fr.R.	**Continental: 4 mm**
	Re.L.	**Continental: 4 mm**	Re.R.	**Continental: 4 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**225/45 R 18 91 W**
Tyre size FR	**224/45 R 18 91 W**
Tyre size RL	**225/45 R 18 91 W**
Tyre size RR	**225/45 R 18 91 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**2**		
Number of charging cables (rapid charge)	**1**		

Bumper F, Dent(s) and scratch(es), Repair and paint (complete)








Windscreen, Stone chip(s), Windscreen repair



Bonnet, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Repair and paint (complete)





Door FL, Dent(s), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s), Acceptable



Bumper R, Scratch(es), Acceptable




Tyre RR, Tear, Replace




Alloy rim RR polished, Scratch(es), Repair and paint (complete)






Door FR, Scratch(es), Acceptable




Alloy rim FR polished, Scratch(es), Repair and paint (complete)








Onderhoudshistorie van: W1K5J8GB4PN338674

ALPHABET

Kenteken	2CMR587
Merk Model	Mercedes CLA250e Sedan Business Solution 1.3i 218pk/cv 4p 8G-DCT
Brandstofsoort	Benzine
Datum deel1	9/19/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
8/25/26	46,176	klein materiaal	
8/25/26	46,176	mercedes assyst b	Uitvoeren
9/9/25	38,726	bougie	Vervangen
9/9/25	38,726	dakgel. smeren	Uitvoeren
9/9/25	38,726	klein materiaal	
9/9/25	38,726	luchtfilter	Vervangen
9/9/25	38,726	mercedes assyst a	Uitvoeren
9/26/24	28,632	klein materiaal	
9/26/24	28,632	mercedes assyst b	Uitvoeren
9/26/24	28,632	remvloeistof	Vervangen
9/26/24	28,632	ruitenwisserrubber vooraan	Vervangen
9/15/23	19,005	20000 km	Uitvoeren
9/15/23	19,005	luchtfilter	Vervangen
9/15/23	19,005	oliezeef	Vervangen