MACADAM











BMW X5 xDrive45e: 2CQW687

Vinnumber:	**WBATA610709M89825**	Versionname:	
First Registrationdate:	**24/10/2022**	Fiscalpower:	
Expertise Mileage:	**128354**	Power Kw:	
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Hybrid Petrol**		
Maintenance	**OK**		
Maintenance	**+ 4600 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		
Registration Certificate Home (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of headlighting	**Headlighting LED**		
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**275/45/20/110 Y**			
	Fr.L.	**Bridgestone: 5 mm**	Fr.R.	**Bridgestone: 5 mm**
	Re.L.	**Bridgestone: 3 mm**	Re.R.	**Bridgestone: 3 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**3.0**
Tyre profile depth RR	**3.0**
Tyre size FL	**275/45 R 20 110 Y**
Tyre size FR	**275/45 R 20 110 Y**
Tyre size RL	**305/40 R 20 112 Y**
Tyre size RR	**305/40 R 20 112 Y**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Number of charging cables (normal)	**1**	Runflat	**Yes**
Number of charging cables (rapid charge)	**1**		

MOT certificate, Missing, Replace



Windscreen, Repaired, Acceptable




Bumper F, Scratch(es), Acceptable




Alloy rim RL polished, Rust, Acceptable




Door RL, Scratch(es), Acceptable




Wing trim FL, Scratch(es), Acceptable




Boot lid covering R, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable




Alloy rim RR polished, Scratch(es), Acceptable




Bodywork, Paint measurement, Acceptable

