



## RENAULT CLIO: GD-879-LN

Vinnumber:	<b>VF1RJA00X68302768</b>	Versionname:	<b>RENAULT CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)</b>
First Registrationdate:	<b>9/12/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>113686</b>	Power Kw:	<b>103</b>
Bodytype:	<b>Berline</b>	Body colour:	<b>White</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Interior colour:	<b>Black</b>
Fueltype:	<b>Petrol</b>	Type of rims (mounted):	<b>Steel</b>
Engine functioning:	<b>Yes</b>	Dashboard color:	<b>Black</b>
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Steel</b>		
Category:	<b>Passenger Car</b>		

## Options

Number of keys total	<b>1</b>	Radio	
Number keys remote	<b>1</b>	Central consol F	
GPS big screen color		Rear parking sensors	
Windows electric F		Seat cover lining	<b>Lining Other</b>
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	<b>Manual climate control</b>		

## Tyres

195/55/16/87 H				
Summer tyres:	Fr.L.	<b>Goodyear: 35%</b>	Fr.R.	<b>Goodyear: 40%</b>
	Re.L.	<b>Goodyear: 20%</b>	Re.R.	<b>Goodyear: 20%</b>
Tyre profile depth FL				<b>5.9</b>
Tyre profile depth FR				<b>5.5</b>
Tyre profile depth RL				<b>7.0</b>
Tyre profile depth RR				<b>6.8</b>
Tyre size FL				<b>195/55 R 16 87 H</b>
Tyre size FR				<b>195/55 R 16 87 H</b>
Tyre size RL				<b>195/55 R 16 87 H</b>
Tyre size RR				<b>195/55 R 16 87 H</b>
Tyre type FL				<b>All seasons</b>
Tyre type FR				<b>All Seasons</b>
Tyre type RL				<b>All seasons</b>
Tyre type RR				<b>All Seasons</b>
Tyre make FL				<b>259</b>
Tyre make FR				<b>259</b>
Tyre make RL				<b>259</b>
Tyre make RR				<b>259</b>

## Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Interior, Stain, Cleaning



Armrest F M, Broken, Replace



Door RL, Dent(s), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Acceptable



Wing RL, Bad repair, Repair and paint (complete)



Bumper F, Scratch(es), Paint



Bumper grille, Unclamped, Dismount/Mount



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Dent(s), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Polish



Door FR, Dent(s), Repair and paint (complete)



Tailgate / Boot, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Paint



Luggage compartment cover, Missing, Replace



Bodywork, Not original part, Remove lettering



# Historique Maintenance

Immatriculation: **GD-879-LN**

Date de 1ère immatriculation: **09/12/2021**

Modèle: **Renault CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
02/02/2026	100.926	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
30/01/2026	99.986	FLEET SOLUTIONS FRANCE	REVISION
	0		FILTRE CLIM RPLT
20/01/2026	99.296	FLEET SOLUTIONS FRANCE	BALAISSUIE GLACE AV
20/01/2026	99.296	FLEET SOLUTIONS FRANCE	REPLACEMENT PNEUS HIVER
	0		GARDIENNAGE
25/04/2025	81.523	RENAULT RETAIL GROUP	PLAQUETTES AV RPLT
	0		LIQUIDE DE FREIN
	0		REVISION
	0		RECYCLAGE
19/04/2025	81.269	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE
19/04/2025	81.269	CONTITRADE FRANCE	GEOMETRIE CTRL
13/05/2024	70.392	RENAULT RETAIL GROUP	LIQUIDE DE REFROIDISSEMENT RPLT
	0		MOYEU DE ROUE RPLT
	0		DIVERS CARROSSERIE
	0		ROULEMENT AVG RPLT
	0		ROULEMENT AVD RPLT
	0		CONDENSEUR DE CLIM RPLT
29/04/2024	70.392	RENAULT RETAIL GROUP	BALAISSUIE GLACE AV
	0		BALAISSUIE GLACE AR
	0		RECYCLAGE
	0		REVISION
23/08/2023	67.054	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE
06/03/2023	43.050	EDINGER	REVISION ET CLIM
17/11/2022	33.212	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE