

# Description form

## Commission


Country of provider

 The Netherlands

License plate:

(chassis number: WF0PXXGCHPMM40628)

Provider: Leasing company



## FORD FOCUS WAGON 1.5 ECOBL. TIT XBNS ECC/NAV/LMV/PDC/LED

Configuration according to lease software: 1.5dci ecoblue titanium x business 88kW

Mileage	182,833 km	Type of vehicle	Passenger car	Empty weight	1295 kg
Tank/ Loading capacity		Colour	Agate Black trendy metallic	VAT/Margin	VAT
Fuel	Diesel	Number of doors	5		
Transmission	Manual transmission	Drive	Front wheel		
Date of first admission	03-05-2021	Number of cylinders	4	Wheelbase	270 cm
Date of first issue NL	03-05-2021	Assets	88 kW	Load capacity	-
First registration	The Netherlands	CO2 emissions	112 g/km	MOT up to and including	03-05-2026

### Standard equipment according to original price list ( may vary, specified options/extras/photos are binding )

Anti-lock Braking System, rear traffic warning, reversing camera, Autonomous Emergency Braking, automatic air conditioning, Apple Carplay/Android Auto, rear armrest, front armrest, Anti-Slip Regulation, automatic speed limiter ISA, luggage cover, tire pressure monitoring system, Brake Assist System, driver airbag, automatically dimming rearview mirror, Bluetooth, on-board computer, collision detection and activation, electrically folding door mirrors, electrically adjustable and heated door mirrors, chrome exterior parts, connected services, cruise control, DAB, roof rails, roof spoiler, automatic dipped headlights, wireless phone charger, electronic brakeforce distribution, electrically operated tailgate with sensor control, electric rear windows, electric front windows, Electronic Stability Program, extra tinted rear glass, collision warning system, hill hold function, rear head airbag(s), front head airbag(s), split-folding rear seats, keyless entry, keyless start, 16" multi-spoke alloy wheels, LED taillights, LED daytime running lights, LED headlights, leather gear lever, adjustable lumbar support(s), 16" alloy wheels, adaptive front fog lights, multimedia preparation, full map navigation system, rear parking sensor, front parking sensor, passenger airbag, radio, rain sensor, lane departure warning with correction, sports seats, voice control, start/stop system, alarm class 1 (immobilizer), height-adjustable driver's seat, height-adjustable passenger seat, leather steering wheel, multifunction steering wheel, adjustable steering wheel, speed-dependent power steering, WiFi, front side airbag(s)

### Options specified by inspector

Metallic paint, Electrically operated tailgate, Climate Control / ECC, 16-inch alloy wheels, Cruise control Standard, Connectivity, Navigation option\_other, Audio option\_other, LED headlights, Park Distance Control front and rear, Reversing camera, Roof rails

## Inspection

### Present at the car

- ✓ Master key
- ✓ Tire repair kit
- ✗ Instruction booklet
- ✓ Parcel shelf/roller cover
- ✗ Spare key
- ✓ Navigation CD/DVD
- ✓ Maintenance booklet (Digital)

### Interior details

Number of seats	: 5	Number of headrests	: 5
Clean inside	: Yes	Normal smell	: Yes

Air conditioning operation : Attention needed, alternative option Specifics regarding starting out : Yes, do not start

**Exterior features**

Clean on the outside : No, wash User scratches : Yes  
Restyling dents : Yes Crushed stone : Yes

**Tyres**

Band	Estimated profile	Kind	Brand	Mate
LV	7 mm	Winter	Continental	205/60 R16
RV	7 mm	Winter	Continental	205/60 R16
LA	7 mm	Winter	Continental	205/60 R16
RA	7 mm	Winter	Continental	205/60 R16

Number of hubcaps/LMVs LMV  
Quantity damaged 0  
Dealer maintained Yes  
Test drive conducted by inspector No  
Has the car ever been used for special purposes? No  
Does the car have a deviating BPM depreciation? No  
Condition details water pump defective  
Technical condition Needs attention  
Motorcycle : Water pump defective

**Additional details**

**Damage**

**Part:** Exterior  
**Description:** Dirty  
**Given solution:** Washing



**Part:** Front bumper  
**Description:** Scratches  
**Solution provided:** Touch-up and polish



**Part:** Rear bumper  
**Description:** Scratches  
**Solution given:** Spraying



**Part:** Rear right fender  
**Description:** Small dent and scratches  
**Solution provided:** Repair and repaint



**Additional photos**



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo



Extra photo

---

## Documents

No documents found.

---