



**OPEL ASTRA: FL-424-NC**

Vinnumber:	<b>W0VBD6EF0KG395326</b>	Versionname:	<b>OPEL ASTRA 1.6 DIESEL 110 EDITION 120 ans (TRANSFO) VF [5P] bvm 6-110CH-6cv (bi-corps VU)</b>
First Registrationdate:	<b>13/11/2019</b>	Fiscalpower:	
Expertise Mileage:	<b>172597</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Berline</b>	Body colour:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Interior colour:	<b>Black</b>
Fueltype:	<b>Diesel</b>	Type of rims (mounted):	<b>Aluminium</b>
Engine functioning:	<b>Yes</b>	Dashboard color:	<b>Black</b>
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Category:	<b>VS</b>		

**Options**

Number of keys total	<b>1</b>	Radio	
Number keys remote	<b>1</b>	Luggage cover	
Windows electric F		Seat cover lining	<b>Lining Other</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	<b>Autom climate control</b>		

**Tyres**

<b>205/55/16/91 H</b>				
Summer tyres:	Fr.L.	<b>Michelin: 25%</b>	Fr.R.	<b>Michelin: 25%</b>
	Re.L.	<b>Michelin: 25%</b>	Re.R.	<b>Michelin: 25%</b>
Tyre profile depth FL				<b>6.5</b>
Tyre profile depth FR				<b>6.6</b>
Tyre profile depth RL				<b>6.5</b>
Tyre profile depth RR				<b>6.5</b>
Tyre size FL				<b>205/55 R 16 91 H</b>
Tyre size FR				<b>205/55 R 16 91 H</b>
Tyre size RL				<b>205/55 R 16 91 H</b>
Tyre size RR				<b>205/55 R 16 91 H</b>
Tyre type FL				<b>All seasons</b>
Tyre type FR				<b>All Seasons</b>
Tyre type RL				<b>All seasons</b>
Tyre type RR				<b>All Seasons</b>
Tyre make FL				<b>261</b>
Tyre make FR				<b>261</b>
Tyre make RL				<b>261</b>
Tyre make RR				<b>261</b>

**Assistance equipment**

Remote ignition key, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Seat cover FL, Dirty, Cleaning



Seat cover FR, Dirty, Cleaning



Alloy rim RL, Scratch(es), Repair/replace (lump sum)



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Door FL, Scratch(es), Paint



Bumper F, Scratch(es), Paint



Bumper R, Scratch(es), Repair and paint (complete)





# Historique Maintenance

Immatriculation: **FL-424-NC**

Date de 1ère immatriculation: **13/11/2019**

Modèle: **Opel ASTRA 1.6 DIESEL 110 EDITION 120 ans (TRANSFO) VF [5P] bvm 6-110CH-6cv (bi-corps VU)**

Date	Kilométrage	Fournisseur	Descriptif
03/03/2026	171.889	FMC BYMYCAR VOIRON	REVISION ET CLIM
15/04/2025	147.866	FMC BYMYCAR GRENOBLE	LAMPE CODE AVD RPLT REVISION ET AIR ET CARBURANT DIVERS ELEC
02/07/2024	123.401	OPL BYMYCAR	ROTULE DE DIRECTION AVD RPLT DISQUES PLAQUETTES AR RPLT DIVERS ECHAPPEMENT GEOMETRIE CTRL DISQUES PLAQUETTES AV RPLT ROTULE DE DIRECTION AVG RPLT
18/03/2024	114.356	OPL BYMYCAR	REVISION
29/09/2023	105.336	SA MONDIAL AUTOS	LAMPE AR RPLT LAMPE RPLT
07/03/2023	95.639	SA MONDIAL AUTOS	REVISION
15/02/2022	86.174	OPPIDUM AUTOMOBILES	HUILE BV CTRL FERMETURE DOSSIER TECHNIQUE VOLANT MOTEUR RPLT TUYAU DE CARBURANT RPLT JOINT COLLECTEUR ADMISSION RPLT RECHARGE CLIM HUILE MOTEUR GEOMETRIE CTRL MOTEUR RPLT
11/02/2022	86.174	OPPIDUM AUTOMOBILES	REVISION DIVERS PLAQUETTES AV RPLT LAMPE AR RPLT
04/06/2021	57.162	OPPIDUM AUTOMOBILES	REVISION PLAQUETTES AR RPLT BALAIS ESSUIE GLACE AV AR REVISION ET CLIM
20/10/2020	30.192	OPPIDUM AUTOMOBILES	ADBLUE

# Historique Maintenance

Immatriculation: **FL-424-NC**

Date de 1ère immatriculation: **13/11/2019**

Modèle: **Opel ASTRA 1.6 DIESEL 110 EDITION 120 ans (TRANSFO) VF [5P] bvm 6-110CH-6cv (bi-corps VU)**

Date	Kilométrage	Fournisseur	Descriptif
			REVISION ET CLIM