



DACIA DUSTER: FR-784-QV

Vinnumber:	VF1HJD40163998568	Versionname:	DACIA DUSTER Confort Blue dCi 115 4x4 (transfo) VF [5P] 6-115CH-6cv (SUV VU)
First Registrationdate:	24/07/2020	Fiscalpower:	
Expertise Mileage:	154383	Power Kw:	85
Bodytype:	SUV	Body colour:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	4 Wheel-drive	Interior colour:	Dark Grey
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Rear parking sensors	
Windows electric F		Seat cover lining	Lining Other
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

215/65/16/102 V				
Summer tyres:	Fr.L.	Michelin: 85%	Fr.R.	Michelin: 85%
	Re.L.	Michelin: 35%	Re.R.	Michelin: 40%
Tyre profile depth FL				2.6
Tyre profile depth FR				2.4
Tyre profile depth RL				5.8
Tyre profile depth RR				5.6
Tyre size FL				215/65 R 16 102 V
Tyre size FR				215/65 R 16 102 V
Tyre size RL				215/65 R 16 102 V
Tyre size RR				215/65 R 16 102 V
Tyre type FL				All seasons
Tyre type FR				All seasons
Tyre type RL				All seasons
Tyre type RR				All seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Seat cover FL, Burned, Replace



Tyre FL, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Wing FL, Scratch(es), Paint



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper moulding F, Deformed / Strained, Replace



Bumper F, Scratch(es), Paint



Wing RR, Dent(s), Repair and paint (complete)



Luggage compartment cover, Missing, Replace



Bumper moulding R, Scratch(es), Replace



Bumper R, Scratch(es), Paint



Bumper moulding RR, Scratch(es), Replace



Bodywork, Not original part, Remove lettering



Historique Maintenance

Immatriculation: **FR-784-QV**

Date de 1ère immatriculation: **24/07/2020**

Modèle: **Dacia DUSTER Confort Blue dCi 115 4x4 (transfo) VF [5P] 6-115CH-6cv (SUV VU)**

Date	Kilométrage	Fournisseur	Descriptif
04/07/2025	128.231	BOUNY	REVISION
	0		ADBLUE
	0		FILTRE CLIM RPLT
	0		LIQUIDE DE REFROIDISSEMENT RPLT
	0		DIVERS FREIN
20/11/2024	107.957	BOUNY	DIVERS ELEC
	0		REVISION ET CLIM
	0		COMMANDE DE CLIM RPLT
	0		CONTROLE TECHNIQUE
11/03/2024	97.426	BOUNY	BATTERIE RPLT
13/10/2023	87.284	BOUNY	LIQUIDE DE FREIN
	0		REVISION ET CLIM ET AIR ET CARBURANT
13/10/2023	87.284	BOUNY	PLAQUETTES AV RPLT
13/10/2023	87.284	BOUNY	LAMPE CODE AVD RPLT
13/10/2022	57.109	BOUNY	REVISION ET CLIM
12/11/2021	29.622	BOUNY	REVISION