



Skoda Enyaq: L575DG

Vinnumber:	TMBJC7NY7MF013169	Versionname:	Enyaq iV 80 150kW/ 82kWh
First Registrationdate:	23/04/2021	Fiscalpower:	
Expertise Mileage:	122168	Power Kw:	150
Bodytype:		Body colour	Black Magic Metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	512
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	2	Lining semi-leather
GPS		Sun Roof electric
Autom climate control		Panoramic roof
Radio multimedia		Rear parking sensors

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 55 / 19 / 105 / V / Aluminium	6,2 mm	Vredestein	All season
	Right	235 / 55 / 19 / 105 / V / Aluminium	6,0 mm	Vredestein	All season
Rear	Left	255 / 50 / 19 / 107 / V / Aluminium	4,5 mm	Vredestein	All season
	Right	255 / 50 / 19 / 107 / V / Aluminium	5,2 mm	Vredestein	All season

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------


Service, Maintenance, Execute



Interior, Dirty, Cleaning



Dashboard, Scratch(es), Smart repair



Door panel FL, Scratch(es), Replace



Door trim FL, Scratch(es), Replace



Door trim RL, Scratch(es), Replace



Door RL, Dent(s), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Bonnet, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper spoiler F, Dent(s) and scratch(es), Replace



Wing RR, Dent(s), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door trim RR, Scratch(es), Replace



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Door trim FR, Scratch(es), Replace



Outer door handle FR, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Kenteken	L575DG
Merk Model	Skoda Enyaq iV 80 150kW/ 82kWh
Brandstofsoort	Elektrisch
Datum deel1	23-04-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
28-03-25	87.761	APK
28-03-25	87.761	Ruitenwischerblad(en) voorzijde
28-03-25	87.761	Vervanging band
24-11-23	52.825	Ruitenwischerblad(en) achterzijde
24-11-23	52.825	Ruitenwischerblad(en) voorzijde
24-11-23	52.825	Sleutelbatterij