



RENAULT Megane Sport Tourer Diesel: 9433-MDY

Vinnumber:	VF1RFB00570664871	Versionname:	Mégane S.T. 1.5dCi Blue Techno EDC 85kW
First Registrationdate:	20/02/2023	Fiscalpower:	
Expertise Mileage:	170534	Power Kw:	
Bodytype:	Berline	Body colour:	White
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Number of keys total	2	Central consol F
Number keys remote	2	Luggage cover
GPS big screen color		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		Roof bar alu
Cruise Control		
Steering wheel multifunction		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

205/50/17/93 V				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/50 R 17 93 V
Tyre size FR				205/50 R 17 93 V
Tyre size RL				205/50 R 17 93 V
Tyre size RR				205/50 R 17 93 V
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Interior, Dirty, Cleaning



Registration document, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door FL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Acceptable



Wing FL, Scratch(es), Repair and paint (complete)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Bumper F, Scratch(es), Repair and paint (complete)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check

