



Expertise

Protocol number: 46623289  
Order No. / Reference: 26727179-1  
Inspection date: 15 Jul 2026

|                        |                    |
|------------------------|--------------------|
| Manufacturer: Skoda    | Model: Enyaq iV 80 |
| VIN: TMBJC9NY8NF034478 |                    |



| Vehicle details                         |                             |
|-----------------------------------------|-----------------------------|
| Manufacturer / Type / Model / Equipment |                             |
| Skoda Enyaq iV 80                       |                             |
| Vehicle Identification number           | TMBJC9NY8NF034478           |
| Mileage (Read)                          | 136,280 km                  |
| First registration                      | 14 Apr 2022                 |
| Number of holders                       | 1                           |
| Next periodical technical inspection    | 03/2027                     |
| (Report on hand)                        |                             |
| Fuel type                               | Electric                    |
| Power                                   | 70 kW                       |
| Gearbox / Number of gears               | Direct drive / 1            |
| Type of drive                           | Rear drive                  |
| Type of vehicle                         | Station wagon               |
| Colour / colour code                    | Reflexsilber metallic (A7W) |
| Doors / Seats                           | 5 / 5                       |
| Upholstery type                         | Leather                     |
| Colour of upholstery                    | Black-Anthracite            |
| Vehicle with smoke odor                 | no                          |



## Vehicle details

|                                                      |                       |                                |                                                            |
|------------------------------------------------------|-----------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>                   | Available / complete  | <b>Next maintenance in</b>     | 618 Tag(e)                                                 |
| <b>Last service on / at</b>                          | 03/2026 at 127,697 km |                                |                                                            |
| <b>Key is / should be</b>                            | 2 / 2                 | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                      |                       | <b>Letter No.</b>              | GJ907396                                                   |
| <b>Previous damage / Accident</b>                    | Detectable            | <b>Repainting</b>              | Detectable                                                 |
| <b>Inspection conditions</b>                         | sufficient            | <b>Lifting equipment / pit</b> | yes                                                        |
| <b>Test drive</b>                                    | Not performed         | <b>Engine function test</b>    | Performed                                                  |
| <b>Manufacturer key number/<br/>type code number</b> | 8004 / AWS 00052      |                                |                                                            |
| <b>Emission standard</b>                             | 2017/1151             | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                        | 2,649 kg              | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 235/55 R19 101T | Summer tyres on Light alloy | Bridgestone  | 6mm / 6mm   |
| 2) | 255/50 R19 103T | Summer tyres on Light alloy | Bridgestone  | 5mm / 5mm   |

### Additional tyres

| #  | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 235/55 R19 101H | Winter tyres on Light alloy | Pirelli      | 7mm / 7mm   |
| 2) | 255/50 R19 103H | Winter tyres on Light alloy | Pirelli      | 5mm / 5mm   |

### Replacement

| Typ | Tyre size | Type of tyre            | Manufacturer | Tread depth |
|-----|-----------|-------------------------|--------------|-------------|
|     | Tirefit   | Expiration date 11/2025 |              |             |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



## Equipment

## Standard equipment

- Storage compartments (Four roof grab handles, rear with coat hooks - Warning vest compartment in the doors - Storage compartments in the front door panels with 1.5l bottle holders - Storage compartments in the rear door panels - Umbrella compartments in the front doors - Ticket holder on the windshield - Ice scraper in the tailgate panel - Coat hooks on the B-pillars - Cup holder in the front center console - Storage compartments in the trunk)
- Evasive steering assist including turning assistant (The turning assistant monitors oncoming vehicles when you turn left (for left-hand drive vehicles). If there is an immediate danger, it brings the vehicle to a standstill and a warning signal sounds.)
- Design Selection Loft (seat covers in fabric/faux leather - decorative trim strips "brushed aluminum" - headliner in grey - front center armrest, including storage compartment - rear center armrest with cup holders and pass-through - floor mats - ambient lighting for front door panels, multicoloured - footwell lighting and illuminated door handle recesses - umbrella)
- Electric windows front and rear (including anti-pinch protection and child safety lock)
- Cruise control
- Transmission: 1-speed (EV)
- Tinted windows
- Heated rear window
- Rear window wiper including windshield washer system
- Automatic interior mirror dimming
- Isofix anchorage on the front passenger seat
- Isofix anchorage on the outer rear seats including top tether
- Climatronic air conditioning (2-zone) (fully automatic, separately adjustable for driver and front passenger, including odor and allergen filter)
- Charging cable for AC charging stations (Mode 3 charging cable, Type 2, 16A) (Fast charging connector (CCS / Combo 2))
- Manual headlight range adjustment
- Package: Drive BASIC (paddle shifters for adjusting recuperation strength - driving profile selection - heated leather steering wheel with multifunction buttons - steering wheel with hands-off detection)
- Radio accessories: SmartLink (Android Auto and Apple CarPlay)
- Radio accessories: Wireless SmartLink
- Rain sensor and driving light assistant with coming and leaving home function
- Tire mobility kit (tire repair spray incl. compressor)
- Tire pressure monitoring
- Rear seat backrest split 60:40, foldable
- Power steering
- Safety lights in the front side doors
- Seats: Front seats height-adjustable including manually adjustable lumbar support
- Speed limiter
- Lane keeping assistant (Lane Assist)
- Airbag, center airbag front
- Airbag for driver and front passenger (passenger airbag can be deactivated)
- Airbag, front and rear head airbags
- Airbag, front side airbags
- acoustic windscreen
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Electrically adjustable, heated and folding exterior mirrors, including automatic dimming.
- Outdoor temperature display
- Hill start assist
- Grey headliner
- Digital instrument cluster (Virtual Cockpit)
- Third brake light
- E-Sound (external speaker for generating a driving sound)
- Electronic parking brake including auto-hold function
- Increased battery charging power max. 125 kW incl. 1 year free monthly basic fee at Ionity
- ESC Electronic Stability Control
- Front radar assist with pedestrian and cyclist detection and city emergency braking function (The front radar assist is a safety system with collision warning: If confronted with an unavoidable collision, it brakes the vehicle to minimize the consequences. It also performs emergency braking if a pedestrian or cyclist attempts to cross the vehicle's path. The front radar assist recognizes from the way the driver moves the vehicle that they are attempting to avoid an obstacle and actively intervenes in the steering to steer around it.)
- Child safety locks on the rear doors
- Removable boot cover
- Front and rear headrests are height-adjustable.
- Paint finish: Solid
- LED headlights with daytime running lights
- LED taillights
- Steering wheel adjustable for height and reach
- Package: Chrome (chrome trim strips on the outside of the side windows - AERO anodized roof rails)
- Package: Parking BASIC (front and rear parking sensors - reversing camera)
- Radio: Infotainment system with capacitive 13" color display (8 speakers - 2 x USB ports (Type-C) at the front - Navigation system preparation - DAB+ digital radio reception - Bluetooth hands-free phone system - Voice control - SmartLink (MirrorLink, Apple CarPlay, Android Auto) - Wireless SmartLink for Apple CarPlay and Android Auto)
- Wheels: 19" Proteus Silver alloy wheels (8Jx19 tires 235/55 R19 101T front, 255/50 R19 103T rear)



- 12V socket - in the trunk
- Traffic sign recognition
- Immobiliser
- Central locking including remote control integrated into the key (EASY START (keyless start-stop system))

- Seat belts (Height-adjustable three-point seat belts in the front - Three three-point seat belts in the rear - Seat belt reminder indicators on the front and rear seats)
- Skoda Care Connect (SOS emergency call function (eCall including automatic activation in the event of an accident with airbag deployment) - Free remote vehicle access to iV-specific functions for 10 years (iV Remote Services Basic) such as starting and stopping the charging process, creating charging plans, setting the interior climate control before starting a journey, etc. - Mobility service (connection option for rapid assistance in the event of a breakdown) - Information service - Free remote vehicle access for 1 year (Remote Access))

### Extra equipment

- Airbag, rear side airbags
- Swiveling trailer hitch (including trailer stabilization)
- Luggage net partition
- Paint finish: Metallic
- Mobile charging station "iV Universal Charger" with interchangeable connection adapters
- Package: Convenience BASIC (KESSY (Keyless Entry and Start-Stop System) - Phonebox with inductive charging function (connection via the external antenna) - Sunset including acoustic side glazing at the front - Extended acoustic measures - Driver fatigue detection - Removable glasses compartment)
- Package: Climate Control PLUS (Heated front and outer rear seats - Heated windshield washer nozzles - Climatronic air conditioning (3-zone), fully automatic, separately adjustable for driver, front passenger and rear passengers including odor and particle filter - Heated windshield)
- Package: Parking PLUS (front and rear parking sensors - reversing camera incl. 360° surround view camera)
- Package: Seating comfort BASIC (electrically adjustable driver's seat with memory function - electrically adjustable lumbar support in the driver's seat)
- Panoramic sunroof, electric (deletion of the glasses compartment in the headliner)
- Bag for charging cable 0000873 17BQ

- ALU WKR 19" Proteus
- Design Selection Suite (leather seat covers - "Piano black" trim strips - grey headliner - front center armrest including storage compartment - rear center armrest with cup holders and pass-through - floor mats - multi-coloured ambient lighting for instrument panel and front door trim - footwell lighting and illuminated door handle recesses - umbrella)
- Package: Driving Assistance BASIC (Adaptive Distance Assist (ACC) - Lane Change and Parking Assist - Proactive Occupant Protection)
- Package: Infotainment PLUS (Navigation system - Infotainment Online 3 years (Online map updates for navigation; display of weather data, news, headlines; charging station and parking space search; Online POI search; Online destination import) - Augmented reality head-up display)
- Package: Light & Sight PLUS (LED matrix headlights incl. AFS and dynamic high beam assist - headlight cleaning system - full LED taillights with animated turn signals - illuminated front grille "Crystal Face")
- Package: Transport (Net program in the trunk incl. charging cable bag - Variable loading floor in the trunk - Remote release of the rear seat backrests in the trunk - Cargo elements in the trunk)
- heat pump

### Brief expert findings

|                      |                                                                                                                                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.    |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle.                     |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                        |
| Engine function test | An engine test run was performed.                                                                                                                                            |



## Value reducing factors

| No. | Component group      | Description                          |
|-----|----------------------|--------------------------------------|
| 1   | Equipment            | Tirefit filler - Due - Replace       |
| 2   | Boot lid / rear door | Emblem - Damaged - Replace           |
| 3   | Rear bumper          | Spoiler - Scratch(es) - Smart repair |
| 4   | Front bumper         | Spoiler - Scratched - Replace        |

## Wear and tear

| No. | Component group | Description                               |
|-----|-----------------|-------------------------------------------|
| 1   | Front bumper    | Front bumper - Stone chips - No deduction |
| 2   | Bonnet          | Bonnet - Stone chips - No deduction       |
| 3   | Vehicle glazing | Windscreen - Stone chips - No deduction   |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Missing parts

### Description

Equipment - Umbrella

## Previous damages

| No. | Previous damage                                           | Extent of damage (Net) |
|-----|-----------------------------------------------------------|------------------------|
| 1   | Side right, Provided by user / customer, from 16 Apr 2025 | 1.426,77 €             |
| 2   | Side right, Provided by user / customer, from 10 May 2024 | 1.694,88 €             |

## Repainting

| No. | Repainting                                                                                    |
|-----|-----------------------------------------------------------------------------------------------|
| 1   | Mudguard - right side, Professionally carried out, Invoice of repair done Non-existent        |
| 2   | Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent |
| 3   | Door - rear right side, Professionally carried out, Invoice of repair done Non-existent       |
| 4   | Door - front right side, Professionally carried out, Invoice of repair done Non-existent      |

## Paint coat thickness measurement

|                        |        |                              |        |
|------------------------|--------|------------------------------|--------|
| Mudguard - right side  | 189 µm | Side panel - rear right side | 272 µm |
| Door - rear right side | 422 µm | Door - front right side      | 204 µm |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

Der beiliegende Winterradsatz ist Bestandteil der Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents



Figure 19: Additional tyres



Figure 20: Navigation



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Damage 1: Equipment: Tirefit filler - Due - Replace



Damage 2: Boot lid / rear door: Emblem - Damaged - Replace



Damage 3: Rear bumper: Spoiler - Scratch(es) - Smart repair



Damage 3: Rear bumper: Spoiler - Scratch(es) - Smart repair



**Damage 4:** Front bumper: Spoiler - Scratched - Replace



**Damage 4:** Front bumper: Spoiler - Scratched - Replace



**Wear and tear 1:** Front bumper: Front bumper - Stone chips - No deduction



**Wear and tear 1:** Front bumper: Front bumper - Stone chips - No deduction



**Wear and tear 1:** Front bumper: Front bumper - Stone chips - No deduction



**Wear and tear 1:** Front bumper: Front bumper - Stone chips - No deduction



**Repainting 1:** Mudguard - right side



**Repainting 2:** Side panel - rear right side



**Repainting 3:** Door - rear right side



**Repainting 4:** Door - front right side