



ARVAL
BNP PARIBAS GROUP

2FPT348

INSPECTION REPORT

End of contract

GENERAL INFO

File	315733
License plate	2FPT348
Vehicle identification number	WBA21EF0305016767
Dossier	2024136062
Make	BMW X1 xDrive 25e 180kW Aut
Mileage	160628
First registration	04/07/2024
client availability date	18/06/2026
inspectionDate	29/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
139	Bumper Rear / Spoiler / Replace	N
283	Bumper Rear / Trim Right / Replace	N
13	Bumper Front // Painting	Y
40	Windshield // Repair	Y
71	Side View Mirror Left // Plastic Repair	N
80	Door Front Left // Smart Repair Small	Y
103	Door Rear Left // Painting	Y
180	Wing Rear Right // Smart Repair Small	Y
193	Door Rear Right // Painting	Y
213	Door Front Right // Painting	Y
221	Side View Mirror Right // Plastic Repair	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wing Rear Right // Smart Repair Small-dent



Windshield // Repair-glass damage



Dashboard / Steering Wheel / Replace-worn



Bumper Front // Painting-stone chipping



Door Rear Left // Painting-scratch




Door Front Left // Smart Repair Small-scratch



Side View Mirror Left // Plastic Repair-scratch




Side View Mirror Right // Plastic Repair-scratch




Door Front Right // Painting-scratch




Door Rear Right // Painting-scratch



Bumper Rear / Trim Right / Replace-scratch



Bumper Rear / Spoiler / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch