MACADAM








Mercedes GLA-Klasse (UKL): 2CCE768

Vinnumber:	**W1N2477121J372849**	Versionname:	**GLA200d Business Solution 2.0d 150pk/cv 5p 8G-DCT**
First Registrationdate:	**1/06/2022**	Fiscalpower:	
Expertise Mileage:	**185147**	Power Kw:	**110**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**OK**		
Maintenance	**BH over 18055km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Type of Tow bar	**No Tow bar**
GPS			
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Winter tyres:	**235/55/18/104 V**			
	Fr.L.	**Firestone: 4 mm**	Fr.R.	**Firestone: 4 mm**
	Re.L.	**Firestone: 5 mm**	Re.R.	**Firestone: 4 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**235/55 R 18 104 V**
Tyre size FR	**235/55 R 18 104 V**
Tyre size RL	**235/55 R 18 104 V**
Tyre size RR	**235/55 R 18 104 V**
Tyre type FL	**Winter**
Tyre type FR	**Winter**
Tyre type RL	**Winter**
Tyre type RR	**Winter**
Tyre make FL	**258**
Tyre make FR	**258**
Tyre make RL	**258**
Tyre make RR	**258**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Steering wheel, Worn, Acceptable




Door panel RL, Scratch(es), Acceptable






Backrest cover FL, Scratch(es), Smart repair





Centre console, Scratch(es), Acceptable




Interior covering A pillar L, Scratch(es), Acceptable





Door panel RR, Scratch(es), Acceptable





Interior covering A pillar R, Scratch(es), Acceptable




Backrest cover FR, Scratch(es), Smart repair






Bumper F, Scratch(es), Spot repair






Door FL, Dent(s) and scratch(es), Spot repair






Central pillar L, Scratch(es), Acceptable




Door RL, Scratch(es), Acceptable






Wing RL, Dent(s), Paintless dent repair




Wing RL, Repaired, Check



Door RL, Repaired, Check



Step L, Scratch(es), Acceptable




Internal boot lining L, Scratch(es), Acceptable







Internal boot lining R, Scratch(es), Acceptable






Luggage compartment cover, Worn, Acceptable





Rear bulkhead lining, Scratch(es), Acceptable




Boot lid covering R, Scratch(es), Acceptable






Tailgate / Boot, Deformed / Strained, Repair and paint (complete)






Step R, Scratch(es), Acceptable




Wing RR, Dent(s) and scratch(es), Acceptable







Door FR, Scratch(es), Acceptable




Alloy rim FR polished, Scratch(es), Acceptable




Onderhoudshistorie van: W1N2477121J372849

ALPHABET

Kenteken	2CCE768
Merk Model	Mercedes GLA200d Business Solution 2.0d 150pk/cv 5p 8G-DCT
Brandstofsoort	Diesel
Datum deel1	6/1/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
9/25/26	181,752	klein materiaal	
9/25/26	181,752	mercedes assyst a	Uitvoeren
3/20/26	154,020	brandstoffilter	Vervangen
3/20/26	154,020	klein materiaal	
3/20/26	154,020	luchtfilter	Vervangen
3/20/26	154,020	mercedes assyst b	Uitvoeren
3/20/26	154,020	remvloeistof	Vervangen
3/20/26	154,020	ruitenwisserrubber achter	Vervangen
3/20/26	154,020	ruitenwisserrubber vooraan	Vervangen
7/4/25	128,828	batterij	Vervangen
7/4/25	128,828	koelwatervloeistof	Bijvullen/-laden
7/4/25	128,828	mercedes assyst a	Uitvoeren
7/4/25	128,828	remblokken achter	Vervangen
7/4/25	128,828	remschijven en blokken vooraan	Vervangen
7/4/25	128,828	ruitenwisserrubber achter	Vervangen
7/4/25	128,828	versnellingsbakolie	Vervangen
11/20/24	103,790	klein materiaal	
11/20/24	103,790	mercedes assyst b	Uitvoeren
11/20/24	103,790	ruitenwisserrubber vooraan	Vervangen
5/24/24	76,935	brandstoffilter	Vervangen
5/24/24	76,935	klein materiaal	Uitvoeren
5/24/24	76,935	luchtfilter	Vervangen
5/24/24	76,935	mercedes assyst a	Uitvoeren
5/24/24	76,935	remvloeistof	Vervangen
1/22/24	59,516	ruitenwisserrubber vooraan	Vervangen
12/19/23	53,890	ruitenwisserrubber vooraan	Vervangen
11/20/23	50,842	klein materiaal	
11/20/23	50,842	mercedes assyst b	Uitvoeren
2/28/23	25,556	klein materiaal	Uitvoeren
2/28/23	25,556	mercedes assyst a	Uitvoeren