ARVAL
BNP PARIBAS GROUP

2AXS514


INSPECTION REPORT

End of contract

GENERAL INFO

File	324350
License plate	2AXS514
Vehicle identification number	TMBJH7NP3N7006921
Dossier	2021 027 156
Make	Skoda Sup.Comb.TDi 150 Clever+
Mileage	115906
First registration	31/08/2021
client availability date	12/10/2026
inspectionDate	16/10/2026








CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	




B
2-AXS-514
JELCAR


DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
66	Wing Front Left // Polish	Y
72	Side View Mirror Left // Painting	N
81	Door Front Left // Smart Repair Medium	Y
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	Y
202	Rocker Panel Right // Painting	N
210	Door Front Right // Smart Repair Small	Y
217	Door Front Right / Trim / Replace	Y
311	Wheel Alloy Front Left // Repair	Y
321	Wheel Alloy Rear Left // Repair	N
533	Trunk Compartment / Side Cover Right / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N

Damage Pictures





Wing Front Left // Polish-scratch




Wheel Alloy Front Left // Repair-scratch




Side View Mirror Left // Painting-scratch




Wheel Alloy Rear Left // Repair-scratch




Trunk Compartment / Side Cover Right / Replace-scratch






Trunk Lid Interior Coating / Complete Panel / Replace-scratch








Bumper Rear // Painting-scratch




Door Front Right / Trim / Replace-scratch




Door Front Right // Smart Repair Small-scratch








Door Front Left // Smart Repair Medium-scratch




Wing Rear Left // Painting-scratch





Bumper Front // Smart Repair Large-scratch + dent




Rocker Panel Right // Painting-scratch + dent