



PEUGEOT 5008: [Redacted]

Vinnumber:	VF3MCYHZRLL052792	Versionname:	1.5 BlueHDi 96kW S&S EAT8 Allure
First Registrationdate:	29/07/2020	Fiscalpower:	
Expertise Mileage:	111607	Power Kw:	96
Bodytype:		Body colour:	White
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3322
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Sun Roof electric:	
Steering wheel multifunctional:		Panoramic roof:	
Seats F heated:		Luggage cover:	
Radio multimedia:		Front parking sensors:	
Type of headlighting:	Headlighting LED	Rear parking sensors:	
Type of GPS:	GPS big screen color	Type of Tow bar:	Tow bar removable
Type of Lining:	Lining semi-artificial leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Tyres

225/55/18/102 V				
Summer tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Emergency spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT: 204,21

Interior, Damaged, Acceptable: 0,00



Windscreen, Repaired, Acceptable 0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 204,21



Door trim RL, Dent(s), Acceptable 0,00



Door RL, Scratch(es), Acceptable 0,00




Door RL, Dent(s) and scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Alloy rim FR polished, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing R, Scratch(es), Acceptable 0,00



Door RR, Dent(s) and scratch(es), Acceptable

0,00

