MACADAM







MINI (UKL): 2EHU122

Vinnumber:	**WMW31DK0302U31335**	Versionname:	**Cooper (F55) 1.5i 136pk/cv 5p Aut.**
First Registrationdate:	**17/10/2023**	Fiscalpower:	
Expertise Mileage:	**58369**	Power Kw:	**100**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**plus 1000 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**175/65/15/84 H**			
	Fr.L.	**Vredestein: 2 mm**	Fr.R.	**Vredestein: 3 mm**
	Re.L.	**Vredestein: 5 mm**	Re.R.	**Vredestein: 4 mm**


Tyre profile depth FL	**2.0**
Tyre profile depth FR	**3.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**175/65 R 15 84 H**
Tyre size FR	**175/65 R 15 84 H**
Tyre size RL	**175/65 R 15 84 H**
Tyre size RR	**175/65 R 15 84 H**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**2480**
Tyre make FR	**2480**
Tyre make RL	**2480**
Tyre make RR	**2480**

Assistance equipment

Bonnet, Bad repair, Repair and paint (complete)







Wing RL, Dent(s), Acceptable




Bumper R, Scratch(es), Acceptable





Bumper trim R, Scratch(es), Acceptable




Alloy rim RR, Scratch(es), Acceptable




Wing RR, Repaired, Check




Bodywork, Paint measurement, Check



Onderhoudshistorie van: WMW31DK0302U31335

ALPHABET

Kenteken	2EHU122
Merk Model	MINI Cooper (F55) 1.5i 136pk/cv 5p Aut.
Brandstofsoort	Benzine
Datum deel1	10/17/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
4/23/26	48,163	BMW/MINI service standaard omvang	Uitvoeren
4/23/26	48,163	klein materiaal	
4/23/26	48,163	remblokken achter	Vervangen
3/3/26	45,372	BMW/MINI service standaard omvang	Uitvoeren
3/3/26	45,372	klein materiaal	
3/3/26	45,372	koelwatervloeistof	Bijvullen/-laden
3/3/26	45,372	remblokken vooraan	Vervangen
3/3/26	45,372	remvloeistof	Vervangen
4/30/25	30,737	batterij	Vervangen
4/30/25	30,737	BMW/MINI service standaard omvang	Uitvoeren
4/30/25	30,737	BMW/MINI voertuigcontrole	Uitvoeren
4/30/25	30,737	klein materiaal	
4/30/25	30,737	service microfilter	Uitvoeren
4/30/25	30,737	service motorolie	Uitvoeren