MACADAM










Volvo XC90: R230VX

Vinnumber:	**YV1LFH5V2P1907667**	Versionname:	**XC90 2.0 T8 PHEV 335kW AWD Ultimate Bright automaat**
First Registrationdate:	**9/12/2022**	Fiscalpower:	
Expertise Mileage:	**184657**	Power Kw:	**228**
Bodytype:		Body colour	**Denim Blue metallic**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Hybrid Petrol**	Parking lot	**380**
Number of seats	**7**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**Yes**		

Options

Number of keys total	**2**	Lining leather	
GPS		Sun Roof electric	
Autom climate control		Panoramic roof	
Radio multimedia		Rear parking sensors	
		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	275 / 45 / 20 / 110 / Y / Aluminium	4,9 mm	Hankook	Summer
	Right	275 / 45 / 20 / 110 / Y / Aluminium	5,0 mm	Hankook	Summer
Rear	Left	275 / 45 / 20 / 110 / Y / Aluminium	5,3 mm	Hankook	Summer
	Right	275 / 45 / 20 / 110 / Y / Aluminium	4,8 mm	Hankook	Summer

Assistance equipment

Number of charging cables (rapid charge)	**0**

Service, Maintenance, Execute



Floor mat(s), Worn, Replace




Wheel arch cover RL, Scratch(es), Replace




Wing FL, Scratch(es), Polish






Door FL, Scratch(es), Repair and paint (complete)




Outer door handle FL, Scratch(es), Repair and paint (complete)




Wheel arch cover FL, Scratch(es), Replace




Windscreen, Stone chip(s), Windscreen repair




Bonnet, Scratch(es), Repair and paint (complete)






Bumper F, Scratch(es), Repair and paint (complete)




Door RR, Dent(s) and scratch(es), Repair and paint (complete)











Wing RR, Scratch(es), Repair and paint (complete)





Wing FR, Scratch(es), Polish




Wheel arch cover FR, Scratch(es), Replace




Charging cable (fast), Missing, Replace



Boot lid covering R, Scratch(es), Replace




Bumper R, Scratch(es), Repair and paint (complete)






Bumper moulding R, Scratch(es), Replace and paint




Onderhoudshistorie van: YV1LFH5V2P1907667

ALPHABET

Kenteken	R230VX
Merk Model	Volvo XC90 2.0 T8 PHEV 335kW AWD Ultimate Bright automaat
Brandstofsoort	Benzine
Datum deel1	12/9/22

Datum reparatie	Kilometerstand	Reparatie omschrijving
4/14/26	154,386	APK
4/14/26	154,386	Bougie
4/14/26	154,386	Luchtfilter
4/14/26	154,386	Onderhoudsbeurt
4/14/26	154,386	Remvloeistof
4/14/26	154,386	Ruitenwisserblad(en) achterzijde
4/14/26	154,386	Ruitenwisserblad(en) voorzijde
4/14/26	154,386	Sleutelbatterij
4/14/26	154,386	Volvo Check aandrijving
4/14/26	154,386	Volvo Check slijtagedelen
11/24/25	140,775	Ruitenwisserblad(en) achterzijde
11/24/25	140,775	Ruitenwisserblad(en) voorzijde
11/24/25	140,775	Sleutelbatterij
9/9/25	130,518	Onderhoudsbeurt
9/9/25	130,518	Volvo Check slijtagedelen
1/29/25	99,367	Onderhoudsbeurt
1/29/25	99,367	Ruitenwisserblad(en) achterzijde
1/29/25	99,367	Ruitenwisserblad(en) voorzijde
1/29/25	99,367	Sleutelbatterij
1/29/25	99,367	Volvo Check slijtagedelen
5/28/24	64,861	Bougie
5/28/24	64,861	Luchtfilter
5/28/24	64,861	Onderhoudsbeurt
5/28/24	64,861	Remvloeistof
5/28/24	64,861	Ruitenwisserblad(en) achterzijde
5/28/24	64,861	Ruitenwisserblad(en) voorzijde
5/28/24	64,861	Sleutelbatterij
5/28/24	64,861	Volvo Check aandrijving
5/28/24	64,861	Volvo Check slijtagedelen
7/13/23	30,114	Onderhoudsbeurt
7/13/23	30,114	Ruitenwisserblad(en) achterzijde
7/13/23	30,114	Ruitenwisserblad(en) voorzijde
7/13/23	30,114	Volvo Check slijtagedelen