



DS 7 CROSSBACK: FN-690-NY

Vinnnumber:	VR1J45GFUKY224798	Versionname:	DS DS 7 CROSSBACK PureTech 180 Automatique Executive VP [5P] bva 8-180CH-9cv (SUV)
First Registrationdate:	6/02/2020	Fiscalpower:	
Expertise Mileage:	154114	Power Kw:	132
Bodytype:	SUV	Body colour:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Dark Grey
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Seats electric F L	
GPS big screen color		Seats electric F R	
GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	Lining Leather
Seats F heated			
Type of climate control	Autom climate control		

Tyres

235/55/18/104 H				
Summer tyres:	Fr.L.	Michelin: 85%	Fr.R.	Michelin: 80%
	Re.L.	Michelin: 50%	Re.R.	Michelin: 45%
Tyre profile depth FL				2.6
Tyre profile depth FR				2.7
Tyre profile depth RL				5.0
Tyre profile depth RR				5.2
Tyre size FL				235/55 R 18 104 H
Tyre size FR				235/55 R 18 104 H
Tyre size RL				235/55 R 18 104 H
Tyre size RR				235/55 R 18 104 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Armrest F M, Tear, Repair/replace (lump sum)			



Tyre FL, Out of tolerance, Replace



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre FR, Out of tolerance, Replace



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door FL, Dent(s), Repair and paint (complete)



Door RL, Dent(s), Repair and paint (complete)



Windscreen, Crack, Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Bonnet, Hail damage, Repair and paint (complete)



Bumper spoiler F, Scratch(es), Paint



Outside rear-view mirror housing R, Scratch(es), Paint



Wing FR, Dent(s), Repair and paint (complete)



Roof pillar R, Dent(s), Repair and paint (complete)



Wing trim RR, Unclashed, Dismount/Mount



Wing RR, Dent(s), Repair and paint (complete)



Reflector, Broken, Replace



Bumper R, Scratch(es), Paint



Luggage compartment cover, Stain, Cleaning



Roof, Hail damage, Repair and paint (complete)



Historique Maintenance

Immatriculation: **FN-690-NY**Date de 1ère immatriculation: **06/02/2020**Modèle: **DS 7 CROSSBACK PureTech 180 Automatique Executive VP [5P] bva 8-180CH-9cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
13/08/2025	135.091	ABCIS PYRENEES BY AUTOSPHERE	REVISION
	0		RECYCLAGE
	0		PLAQUETTES AV RPLT
	0		BALAISS ESUIE GLACE AV
	0		FILTRE CLIM RPLT
	0		FILTRE A AIR RPLT
	0		BOITIER D ALLUMAGE RPLT
	0		DIVERS CLIM
18/07/2024	108.125	OUEST AUTOMOBILES DISTRIBUTION	FILTRE CLIM RPLT
	0		DIVERS MOTEUR
	0		REVISION
23/05/2024	105.541	RDVL	CONTROLE TECHNIQUE
19/07/2023	83.113	OUEST AUTOMOBILES DISTRIBUTION	REVISION
	0		DISQUES PLAQUETTES AV RPLT
	0		PLAQUETTES AR RPLT
	0		BALAI ESUIE GLACE AR
	0		BALAISS ESUIE GLACE AV
	0		FILTRE CLIM RPLT
	0		FILTRE A AIR RPLT
	0		BOITIER D ALLUMAGE RPLT
17/05/2022	49.803	OUEST AUTOMOBILES DISTRIBUTION	REVISION ET CLIM
	0		LIQUIDE DE FREIN
27/05/2021	24.361	OUEST AUTOMOBILES DISTRIBUTION	REVISION