

## Expertise

Protocol number: 45497878  
Order No. / Reference: 26324985  
Inspection date: 15 May 2026

Manufacturer: Skoda

Model: Octavia Combi 2.0 TSI RS

VIN: TMBJV8NX5SY156582



### Vehicle details

#### Manufacturer / Type / Model / Equipment

Skoda Octavia Combi 2.0 TSI RS

**Vehicle Identification number** TMBJV8NX5SY156582

**Mileage (Read)** 24,465 km

**First registration** 23 Jul 2025

**Number of holders** 1

**Next periodical technical inspection** 07/2028

(Report not on hand)

**Power / Engine displacement** 195 kw / 1,984 ccm

**Fuel type / Cylinder** Petrol / 4

**Gearbox / Number of gears** Automatic / 7

**Type of drive** Front drive

**Type of vehicle** Station wagon

**Colour / colour code** Patina-Grau

**Doors / Seats** 5 / 5

**Upholstery type** Cloth / leather combination

**Colour of upholstery** Black-Red

**Re-import** no

**Vehicle with smoke odor** no

**readiness to drive** Roadworthy



## Vehicle details

<b>Maintenance booklet / proof</b>	Non-existent	<b>Next maintenance in</b>	5,300 km
<b>Key is / should be</b>	2 / 2	<b>FZG documents</b>	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		<b>Letter No.</b>	HQ776062
<b>Previous damage / Accident</b>	None detectable	<b>Repainting</b>	None detectable
<b>Inspection conditions</b>	sufficient	<b>Lifting equipment / pit</b>	yes
<b>Test drive</b>	short drive on the company premises	<b>Engine function test</b>	Performed
<b>readiness to drive</b>	Roadworthy		
<b>Manufacturer key number/ type code number</b>	8004 / AYN 00039		
<b>Emission standard</b>	EURO6;WLTP;EB;PI/CI;M, N1, N2	<b>fine dust sticker</b>	
<b>Permitted total weight</b>	1,900 kg	<b>Empty weight</b>	

## Tyres

### Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R18 91Y	Summer tyres on Light alloy	Bridgestone	6mm / 5mm
2)	225/45 R18 91Y	Summer tyres on Light alloy	Bridgestone	5mm / 6mm

### Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R18 95V	Winter tyres on Light alloy	Pirelli	6mm / 6mm
2)	225/45 R18 95V	Winter tyres on Light alloy	Pirelli	7mm / 7mm

### Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	125/70 R18 99M	Summer tyres on Steel	Sonstige	3 mm

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**



## Equipment

### Equipment

- Klimaautomatik

|



## Standard equipment

- Storage compartment in the luggage compartment
- Adaptive cruise control (ACC) with a control range up to 210 km/h
- Airbag, head airbags
- Airbag: Center airbag front
- Traction control (ASR)
- Electrically adjustable, heated and folding exterior mirrors
- Cup holders in the front center console
- Glasses compartment in the headliner
- black headliner
- Anti-theft alarm system with interior monitoring and tilt sensor
- Dynamic Light Assist
- Electro-mechanical front axle differential lock (VAQ)
- Electronic transverse differential lock (XDS+)
- Driving profile selection
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Front and rear footwell lighting
- Removable, semi-automatic luggage compartment cover
- Cruise control system
- Tinted windows
- Rear window wiper including windshield washer system
- Interior mirror automatically dimming
- Kessy, keyless entry and start-stop system
- Child safety lock for rear doors & windows, electric
- Comfort opening including electric tailgate operation
- Crossroad Assist
- Paint finish: Special paint finish, solid color
- Remote release of the rear seat backrests in the trunk
- Steering wheel: Sport design steering wheel
- Reading lights two at the front
- Matrix LED headlights
- Engine drag torque control (MSR)
- Fatigue detection
- Otto particulate filter
- Front and rear parking sensors
- Progressive steering
- Radio accessories: 2 x USB charging ports in the rear and USB charging port in the rearview mirror
- Radio accessories: Digital radio reception DAB+
- Radio accessories: Wireless & Wired SmartLink
- Rain sensor and driving light assistant (Easy Light Assist)
- Tire mobility kit
- Rear view camera
- Seat belts
- Seats: Heated front seats
- Seats: Sports seats with integrated headrests in the front and height-adjustable headrests in the rear.
- Seats: Front seats are height-adjustable
- ŠKODA Infotainment Online & Connect
- Storage compartments
- Airbag, driver and passenger
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Anti-lock braking system (ABS)
- Evasive steering and turning assistant
- Exterior mirrors painted black, door handles in body color
- Hill start assist
- roof grab handles four
- AERO roof rails in gloss black
- Digital Cockpit Plus
- Third brake light
- Ice scraper in the fuel filler flap
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC)
- Chassis: Sport chassis
- Front radar assistant (Front Assist)
- Front splitter and rear diffuser in black
- Luggage compartment lighting with 2 lamps
- Intelligent Speed Assist (ISA)
- Transmission: 7-speed dual-clutch transmission (DSG)
- Heated rear window
- Interior: Design Selection RS
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Climatronic air conditioning (2-zone)
- Fuel tank 50 l
- Black radiator grille frame
- LED taillights in crystal glass look
- Steering wheel: height and reach adjustable
- Steering wheel: Paddle shifters on the steering wheel
- Dynamic and automatic headlight range control
- Front center armrest, including storage compartment
- Multi-collision brake
- Navigation system
- Package: Simply Clever
- Pedals in stainless steel look
- Radio: Music system
- Radio accessories: 8 speakers
- Radio accessories: Bluetooth hands-free system
- Radio accessories: Voice control
- Umbrella and broom compartments in the front doors
- Tire pressure monitoring
- Wheels: 18" Comet alloy wheels, black
- Headlights washer / wiper system
- Safety lights in the front side doors
- Seats: Rear seat backrest split 60:40, foldable
- Seats: Pockets on the backs of the front seats including smartphone pockets



- Sports exhaust system
- Lane keeping assistant (Lane Assist)
- 12V socket in the trunk
- Telephone: Phonebox with inductive charging function (connection via external antenna)
- Front door sill trims
- Traffic sign recognition
- Lashing eyes in the trunk
- Preparation for a trailer hitch
- Immobiliser
- Decorative trim in piano black around the air vents

- SKODA Connect
- Sun visors with illuminated make-up mirror on driver and passenger side
- Lane change and parking assist as well as exit warning
- RS bumper and rear spoiler
- Textile floor mats
- Travel Assist
- Glazing: Acoustic glazing in the front side windows and Sunset
- Preparation for alcohol immobilizer
- Wash water level check
- Central locking including remote control integrated into the key and EASY Start

### Extra equipment

- Interior features: Design Selection RS Lounge (microfiber leather interior combined with high-quality materials - instrument panel center section with microfiber cover - door panels with microfiber cover - electrically adjustable front seats with memory function - ergonomic sports seats in front - massage function - extendable leg rest)
- Paintwork: Individual
- Package: Winter (Heated steering wheel - Heated windshield)
- Panoramic sunroof, electric (deletion of the glasses compartment in the headliner)
- Radio accessories: CANTON sound system (12 speakers (10 speakers, 1 center speaker, 1 subwoofer) - including steel spare wheel)

### Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	A short maneuvering and shunting exercise was carried out on the company premises.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

### Wear and tear

No.	Component group	Description
1	Trim / covers	Door trim - front left side (kleine Beschädigung) - Damaged - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

### Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: VIN



Figure 13: Mounted tyres




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



**Wear and tear 1:** Trim / covers: Door trim - front left side (kleine Beschädigung) - Damaged - No deduction



**Wear and tear 1:** Trim / covers: Door trim - front left side (kleine Beschädigung) - Damaged - No deduction