



PEUGEOT 308 3

-	
VIN	VR3F3DGXTPY629953
Première immatriculation	17/10/2023

DÉTAILS DE L'INSPECTION

Date de l'inspection	12/02/2026 14:44:10	Adresse d'inspection	
----------------------	---------------------	----------------------	--

INFORMATIONS SUR LE VÉHICULE

VIN	VR3F3DGXTPY629953	Transmission	Avant
Type de carrosserie	Berline	Nbre sièges	5
Nbre portes	5	Nombre appuis-têtes	5
Première immatriculation	17/10/2023	Couleur intérieur	Noir
Type de carburant	Hybride rechargeable	Couleur carrosserie	Gris
Marque	PEUGEOT	Catégorie	Vehicule particulier
Modèle	308 3	Couleur tableau de bord	Noir
Boîte de vitesse	Automatique		

DOCUMENTS ET CLÉS

Carte d'entretien	Oui	Certificat immatriculation (original)	Original
Nbre clés total	2	Certificat immatriculation (original)	Oui
Nbre clés télécommandes	2	Entretien	Oui
Manuel d'utilisation	Oui		

OPTIONS

Nature de peinture	Metallisé
--------------------	-----------

DAMAGES

Interior



1 | Seat cover FL

Damage type	Stain
Repair mode	Cleaning

Exterior



2 | Alloy rim FL bitone/polychrome

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



3 | Alloy rim RL bitone/polychrome

Damage type	Scratch(es)
Repair mode	Acceptable





4 | Tyre RR

Damage type	Out of tolerance
Repair mode	Replace



5 | Alloy rim RR bitone/polychrome

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



6 | Alloy rim FL bitone/polychrome

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)





7 | Tyre FR

Damage type	Tear
Repair mode	Replace



8 | Tyre RL

Damage type	Out of tolerance
Repair mode	Replace



9 | Door FL

Damage type	Dent(s) and scratch(es)
Repair mode	Acceptable



10 | Door RL

Damage type	Scratch(es)
Repair mode	Acceptable




11 | Wing RL

Damage type	Scratch(es)
Repair mode	Paint



12 | Bumper F

Damage type	Scratch(es)
Repair mode	Paint



13 | Windscreen

Damage type	Stone chip(s)
Repair mode	Windscreen repair



14 | Wing RR

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



15 | Bumper R

Damage type	Scratch(es)
Repair mode	Polish

Commercial photos

