



RENAULT EXPRESS: 4983-MBB

Vinnumber:	VF1RJK00469591565	Versionname:	Confort 1.5 Blue dCi 70 kW (95 cv) furgón derivado de turismo 70kW 4P manual
First Registrationdate:	6/09/2022	Fiscalpower:	
Expertise Mileage:	37608	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2		
Windows electric F:			
Cruise Control:			
Steering wheel multifunctional:			
Type of climate control:	Manual climate control		

Tyres

185/65/15/88 H				
Summer tyres:	Fr.L.	Nexen: 4 mm	Fr.R.	Nexen: 4 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm
Tyre profile depth FL:				4.0
Tyre profile depth FR:				4.0
Tyre profile depth RL:				7.0
Tyre profile depth RR:				7.0
Tyre size FL:				185/65 R 15 88 H
Tyre size FR:				185/65 R 15 88 H
Tyre size RL:				185/65 R 15 88 T
Tyre size RR:				185/65 R 15 88 T
Tyre type FL:				Summer
Tyre type FR:				Summer
Tyre type RL:				Summer
Tyre type RR:				Summer
Tyre make FL:				1957072
Tyre make FR:				1957072
Tyre make RL:				259
Tyre make RR:				259

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
--------------	------------	-------	------------

Outside rear-view mirror housing L, Scratch(es), Paint



Bumper F, Scratch(es), Paint



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Windscreen, Stone chip(s), Replace



Outside rear-view mirror housing R, Scratch(es), Paint



Sliding door R, Dent(s), Repair and paint (complete)



Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)



Rear panel, Scratch(es), Paint



Bumper R, Scratch(es), Paint



Tyres, No damage, Check



