



Vehicle History Report

PORSCHE PANAMERA

Vehicle reference:

WP0ZZZ97ZNL140006

Number of doors:

5

Quick Check


Damage

This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.

 **Damage**

Import

Not a private import

 **No issues reported**

Located in Italy




Vehicle age

**4 years
5 months**

Damage Overview

07/2020 Damage reported



Affected area:


- Vehicle damaged on all sides

Severity scale:
Severe


Damage type/cause:
 Not available

Reported on:
 07/2020

Reported in:
 Italy



01/2024 Damage reported



Affected area:


- Front
- Left
- Left front
- Right
- Right front

Severity scale:
Severe

Damage type/cause:
 Not available

Reported on:
 01/2024

Reported in:
 Italy




Damage Glossary

Damage

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

Mileage Check

Last odometer reading 85 041 km Reported on: 2025-10-08	Average mileage 21 245 km/year	Average mileage for similar cars 15 040 km/year
---	---	--



✓ No issues indicated: The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

Owners BETA



Owner 1 in Italy

Purchase year:	2021
Length of use:	4 years
Type of owner:	Leasing company
Damage reported on:	01/2024

Owner 2 in Italy

Purchase year:	2025
Type of owner:	Commercial business

History information

Date	Mileage	Event
07/2020		Damage reported in Italy
2021-10-08		Leasing reported Registered in Italy New owner reported Owner type: leasing company
01/2024	51 463 km	Odometer reading reported
01/2024		Damage reported in Italy
2025-10-08	85 041 km	Inspected in Italy Inspection valid until 2027-10-31
2025-10-14		New owner reported Owner type: commercial

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

Technical details

Engine and performance

Fuel type

Other information

Number of doors

5

CARFAX Glossary

Average Mileage

Average Mileage is not the actual odometer reading for this car, but an estimate of how many kilometers an average car of this make, model, fuel type and age would be expected to have if used solely for personal use. The actual mileage for this particular car will indicate if it has been driven more or less than average and may be a factor to help you determine its value

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our [Terms and conditions.](#)