



Expertise

Protocol number: 46227492
Order No. / Reference: 26521521
Inspection date: 29 Jun 2026

Manufacturer: Volkswagen

Model: Transporter T6.1 DSG Kurz

VIN: WV1ZZZ7HZMH013808



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen Transporter T6.1 DSG Kurz	
Vehicle Identification number	WV1ZZZ7HZMH013808
Mileage (Read)	184,107 km
First registration	26 Oct 2021
Number of holders	1
Next periodical technical inspection	10/2027
(Report on hand)	
Power / Engine displacement	110 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candyweiß
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	Next maintenance in	0 km
Last service on / at	10/2025 at 171,786 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FU703087
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / BXU 55196		
Emission standard	EURO6;WLTP;CI;PI/CI;N1 III, N2	fine dust sticker	
Permitted total weight	2,800 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 109T	Winter tyres on Steel rim with wheel cover	Falken	5mm / 5mm
2)	215/65 R16 109T	Winter tyres on Steel rim with wheel cover	Falken	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 109T	Summer tyres on Steel	Continental	5mm / 5mm
2)	215/65 R16 109T	Summer tyres on Steel	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit			

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage and stowage boxes
- Electrically adjustable and heated exterior mirrors
- Hill Start Assist
- third brake light
- Electronic Stability Program
- Fresh air system with multi-stage fresh air blower
- Tailgate without window
- Heating and ventilation system in the driver's cab
- Headrests (2)
- Paint finish: Solid
- Multi-collision brake
- Particulate filter: Soot particle filter for diesel engines
- Radio: Digital radio reception (DAB+)
- Wheels/Tires: 205/65 R 16 C 107/105 T, optimized for low rolling resistance
- Wheels: Tire Mobility Set
- Keys for locking system: 2 remote control flip keys
- Crosswind assist
- Seat belts: Three-point automatic seat belts
- Daytime running light
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking with remote control and interior operation
- Airbag for driver and front passenger
- Exterior mirrors, left and right convex
- Floor coverings: Rubber floor covering in the driver's cab
- Tachometer
- Electric windows, front
- Transmission: DSG (dual-clutch transmission), 7-speed automatic
- Child safety lock, electrically operated
- Fuel tank with a 70-liter tank capacity
- Headlight range control
- Non-smoking version
- Upholstery: Seat covers in fabric, "Double Grid" design
- Radio accessories: 2 speakers (wideband)
- Wheels/Tires: Steel wheels 6.5 J x 16 in 20-hole design
- Wheels/Tire Accessories: Wheel covers for 16" wheels
- Sliding door in the passenger/cargo compartment: sliding door on the right
- electromechanical power steering
- Start-stop system
- Telephone: Mobile phone interface
- Lashing eyes for securing cargo
- Green thermal insulation glazing
- Registration as a truck



Extra equipment

- "Premium" multifunction display with multicolor screen and fatigue detection
- "Transporter" lettering on the fender, no lettering on the rear
- Auxiliary heater: Air auxiliary heater and PW3
- Batteries: 2nd battery with isolation relay, maintenance-free
- Bott facility
- LED headlights and LED taillights (LED headlights with LED daytime running lights - automatic headlight range control - red LED taillights)
- Package: Comfort Package Plus (2 12-volt sockets, air conditioning in the driver's cab with manual control, fabric seat covers, "Bricks" design, 1 waste bin for the door pockets in the driver's cab, additional soundproofing measures in the driver's cab, height adjustment for the left single seat in the driver's cab, glove compartment lid with light, foldable grab handle on the roof frame on the passenger side, storage compartments on the driver's cab seats, reading light, sun visors with mirrors (front/rear), grab handle (front/rear), manual lumbar support for the left single seat in the 1st row of seats)
- Seat configuration - 5. Armrests: Armrests for the left seat in the driver's cab
- Tailgate with window, heated (tailgate with window cutout - rear window, heated - safety interior mirror, dimmable)
- Telephone: Mobile phone interface "Comfort" (with inductive charging function)
- Total weight: Permissible total weight 3.2 t with reinforced 16" steel wheels (4 steel wheels 6.5 J x 16 - Permissible total weight 3,200 kg - Suspension and damping, for vehicles with 3.2 t permissible total weight - On-board tools and jack, reinforced, for vehicles with 3.2 t GVW)
- Windows: Front window and closed rear side wall, in the cargo/passenger compartment, right
- Cruise control system including speed limiter
- Fleet management system interface (electrical terminal block and function control unit 1 with body manufacturer (ABH) programming)
- Fuel tank with 80 l tank capacity
- Glove compartment with light
- Light and visibility (interior safety mirror, automatically dimming - daytime running lights with automatic headlight control, "Leaving home" function and manual "Coming home" function - intermittent wiper control with rain sensor for the windshield wipers)
- Partition walls: High partition wall with fixed window and 8 lashing rings for securing cargo (partition wall, high, with window - without child safety lock in passenger compartment - lashing rings for securing cargo, reinforced (ISO 27956))
- Power outlets: 2 12-volt sockets in the dashboard
- Radio navigation system "Discover Media" including "Streaming & Internet" (voice control - 2 USB interfaces (Type C) in the dashboard - "Discover Media" radio navigation system with 20.3 cm (8 inch) touchscreen including "Streaming and Internet" - navigation function/preparation - 4 speakers: 2 tweeters, 2 woofers - Wired & Wireless App-Connect)
- Rear window with heat-insulating glazing, heated, and rear window wiper/washer system
- Seat configuration - 4. Lumbar support: Lumbar support (electrically adjustable) for single seat in the driver's cab, left.
- Seat heating for driver's seat, left, adjustable
- Tailgate with window cutout and closing aid
- Wheels/Tires: 215/65 R 16 C 106/104 T rolling resistance optimized
- Wheels/Tires: Tire pressure monitoring system (direct measuring)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance (Nachweis unvollständig, Inspektion fällig) - No evidence - No deduction
2	Body	Body - Glued / labelled - De-glue / neutralise
3	Misc.	Inspection / maintenance - Due - Perform
4	Bonnet	Bonnet (Übermäßige Steinschläge) - Stone chips - Paint



Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction
3	Interior	Interior - Scratch(es) - No deduction
4	Rear bumper	Rear bumper - Scratch(es) - No deduction
5	Wing mirror - right side	Cap - Scratch(es) - No deduction
6	Side panel - rear right side	Side panel - Scratch(es) - No deduction
7	Boot lid / rear door	Boot lid - Scratch(es) - No deduction
8	Sill - right side	Sill - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - Tirefit complete

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Comments

Der montierte Winterradsatz ist nicht Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Damage 2: Body: Body - Glued / labelled - De-glue / neutralise



Damage 2: Body: Body - Glued / labelled - De-glue / neutralise



Damage 3: Misc.: Inspection / maintenance - Due - Perform



Damage 4: Bonnet: Bonnet (Übermäßige Steinschläge) - Stone chips - Paint



Damage 4: Bonnet: Bonnet (Übermäßige Steinschläge) - Stone chips - Paint



Damage 4: Bonnet: Bonnet (Übermäßige Steinschläge) - Stone chips - Paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WV1ZZZ7HZMH013808

Hersteller / Modell: VOLKSWAGEN VOLKSWAGEN Transporter T6.1 DSG Kurz

Datum	KM-Stand	Beschreibung
22.10.2025	171.786	AU; Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben hinten; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
11.11.2024	151.040	Reparatur Sonstiges; Systemtest/Eigendiagnose
17.05.2024	141.009	Getriebeöl ern/prüfen; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
03.05.2024	127.091	Reparatur Sonstiges; Systemtest/Eigendiagnose
26.10.2023	103.583	AU; Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
08.02.2023	64.459	Bremsbelagfühler ern; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Getriebeöl ern/prüfen; Motoröl b. Wartung; Regelwartungsdienst
30.06.2022	32.967	Motoröl b. Wartung; Regelwartungsdienst