


MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2026		Claim number				Code / Agency				Date accident 09/06/2026							
				Expert code		Adjuster code				Policy number				Injured person can recover the VAT							
Date assignment 09/06/2026		Date first survey 09/06/2026		Place VENEZIA		C/O VAR		Repairs TO START		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)														Formerly plate							
Lessee / Co-owner														Date of overhaul							
Vehicle (Brand - Model - Version) PEUGEOT 3008 BlueHDI 130 EAT8 S&S Allure								Plate GF716RW		Vin Chassis VF3MCYHZUMS059794				First Registration 14/05/2021							
Usage status NON CONOSCIUTO		Km 87412		Tyres % 50		Color NERO		Type of enamel METALLIZED/DOUBLE				Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0										Wheelbase		Seats No. 0		Axles 0	
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts * (VAT excluded)			
								Dif		Time		Dif		Time		Dif		Time			
1		98252889XT		Front wheel arch trim				L		S		S		S							
1		1675868480		Front bumper						M				M							
1		9812317280		Rear door				L		L				L							
1		1617342980		rear mudguard				L		L		L		L							
1		9812317080		Rear door				R		L		L									
1		9812306280		Front door				R		L				L							
1		Codice Ricambio		Cerchio in lega ant. - Rettifica				L													
1		Codice Ricambio		Seconda chiave																	
1		Codice Ricambio		Mod. lat. paraurti ant. - PRM				L													
1		Codice Ricambio		Mod. arco. pass.ta post. - PRM				L													
1		Codice Ricambio		Ricarica batteria																	
1		Codice Ricambio		Diagnosci																	
1		Codice Ricambio		---																	
1		Codice Ricambio		NOTE:																	
1		Codice Ricambio		Quantificati i danni visibili e/o potenzialmente correlati con																	
1		Codice Ricambio		quanto rilevabile; riserva danni occulti.																	
1		Codice Ricambio		---																	

New for old value (N)	Remarks
	Pneum. INV. Dunlop 225/55 R18. Vhl sporco. "Modalità economica d'energia attiva" Alert avaria freno a mano; spia service e altre spie attive. Evasa secondo direttive Note in corpo perizia: