



Opel Corsa: N132VT

Vinnumber:	VXKUHZKXZM4374196	Versionname:	Corsa-E 3 fase lader 100kW / 50kWh Edition
First Registrationdate:	29/12/2021	Fiscalpower:	
Expertise Mileage:	79078	Power Kw:	100
Bodytype:		Body colour	White Jade
Gearbox:	Automatic	Paint type	Opaque
Transmission:		Type of rims (mounted)	Steel
Fueltype:	Electric	Parking lot	568
Number of seats	5		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	2
Autom climate control	
Radio multimedia	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 55 / 16 / 91 / V / Steel	5,8 mm	Vredestein	All season
	Right	195 / 55 / 16 / 91 / V / Steel	5,2 mm	Vredestein	All season
Rear	Left	195 / 55 / 16 / 91 / V / Steel	6,2 mm	Vredestein	All season
	Right	195 / 55 / 16 / 91 / V / Steel	6,2 mm	Vredestein	All season

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Door RL, Scratch(es), Repair and paint (complete)



Door RR, Bad repair, Repair and paint (complete)




Door FR, Bad repair, Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Dent(s), Repair and paint (complete)



Roof, Bad repair, Repair and paint (complete)



Kenteken	N132VT
Merk Model	Opel Corsa-E 3 fase lader 100kW / 50kWh Edition
Brandstofsoort	Elektrisch
Datum deel1	29-12-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
08-07-26	78.174	Boordcomputer
08-07-26	78.174	Onderhoudsbeurt
04-09-25	60.254	Onderhoudsbeurt
04-09-25	60.254	Sleutelbatterij
21-08-25	59.096	Reparatie band(en)
25-07-25	57.475	APK
25-07-25	57.475	Ruitenwisserblad(en) voorzijde
12-12-24	15.448	Tractiebatterij lader
08-03-24	34.746	Onderhoudsbeurt
23-03-23	13.448	Onderhoudsbeurt