



RENAULT CLIO: GD-888-KX

Vinnumber:	VF1RJA00X67889852	Versionname:	RENAULT CLIO Business E-Tech hybride 140 -21N
First Registrationdate:	8/12/2021	Fiscalpower:	VP [5P] bva 6-140CH-5cv (bi-corps)
Expertise Mileage:	134820	Power Kw:	103
Bodytype:	Berline	Body colour:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Interior colour:	Anthracite
Fueltype:	Hybrid	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Anthracite
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Headlights Xenon/LED/Laser	
Windows electric F		Rear parking sensors	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

	195/55/16/91 V			
Summer tyres:	Fr.L.	Goodyear: 45%	Fr.R.	Goodyear: 45%
	Re.L.	Goodyear: 20%	Re.R.	Goodyear: 30%
Tyre profile depth FL				5.3
Tyre profile depth FR				5.3
Tyre profile depth RL				6.8
Tyre profile depth RR				6.2
Tyre size FL				195/55 R 16 91 V
Tyre size FR				195/55 R 16 91 V
Tyre size RL				195/55 R 16 91 V
Tyre size RR				195/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Armrest F M, Broken, Replace



Interior, Stain, Cleaning



Wing FL, Dent(s), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Polish



Bumper F, Scratch(es), Paint



Luggage compartment cover, Missing, Replace




Rear roof pillar covering R, Broken, Replace



Rear bulkhead lining, Scratch(es), Replace



Boot lid covering R, Scratch(es), Replace



Wiper arm rear, Incomplete, Replace



Bumper R, Deformed / Strained, Repair and paint (complete)



Shutter / cover R, Missing, Replace



Historique Maintenance

Immatriculation: **GD-888-KX** Date de 1ère immatriculation: **08/12/2021**

Modèle: **Renault CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
23/04/2026	130.254	FLEET SOLUTIONS FRANCE	REPLACEMENT PNEUS ETE
	0		REPLACEMENT PNEUS ETE
	0		REPLACEMENT PNEUS ETE
	0		REPLACEMENT PNEUS ETE
18/03/2026	126.359	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
17/03/2026	125.724	AVENIR O'THAU	RECYCLAGE
	0		REVISION ET CLIM ET AIR ET BOUGIES
	0		LIQUIDE DE FREIN
	0		BALAI ESSUIE GLACE AR
25/02/2025	92.852	CONTITRADE FRANCE	REPARATION DE ROUE
19/02/2025	91.247	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE
	0		PERMUTATIONS PNEUS
12/02/2025	91.178	RNO MURET	BALAIS ESSUIE GLACE AV
07/02/2025	91.178	RNO MURET	REVISION ET CLIM
14/05/2024	61.848	RNO MURET	REVISION
08/12/2023	49.089	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS 4 SAISONS
04/05/2023	29.546	MURET NORD AUTOMOBILES	BALAIS ESSUIE GLACE AV AR
	0		REVISION ET CLIM
	0		PLAQUETTES AV RPLT
	0		LAMPE RPLT
14/02/2023	21.935	CONTITRADE FRANCE	REPLACEMENT PNEUS 4 SAISONS