SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Marcel Peeters

2-FFE-334

2-FFE-334 · TS 1.8 Hybrid Dynamic + Business pack · 4 November 2026 · Zaventem Brussel

Specifications

License Plate Number	2-FFE-334
Manufacturer	TOYOTA
Model	Corolla
Model Versions	TS 1.8 Hybrid Dynamic + Business pack
Body Type	Station Wagon
Color	Blue
Paint Type	Metallic
Production Year	2024
KW	72
Fuel Type	Hybrid Gasoline

VIN	SB1ZB3AE30E074002
Cylinder Capacity	1.798 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	18-04-2024
First Registration	18-04-2024
Odometer	67.225 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	5

Images































Accessories

ABS	Electric windows front
Airbags	Electrically adjustable exterior mirrors
Alloy wheels	Fog lights
Audio System	Front & rear parking sensors
Automatic air conditioning	Leather steering wheel
Bluetooth car kit	Navigation system
Central door locking	Rear view camera
Centre armrest	Roller cover / parcel shelf
Cruise control	Seat heating
Electric rear windows	Steering wheel multifunction

Condition

Condition exterior	Adequate	Last maintenance odometer	32.710
Condition interior	Adequate	Previous Repairs	Unknown
Last Maintenance	15-07-2025		

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 mm	Pirelli	205 mm	55 mm	16 inch	All Season
Rear Left	7 mm	Semperit	205 mm	55 mm	16 inch	All Season
Front Right	6 mm	Pirelli	205 mm	55 mm	16 inch	All Season
Rear Right	7 mm	Semperit	205 mm	55 mm	16 inch	All Season
Spare Tire Type	Compressor					

Damages





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Small scratch(es)	Polish	No





Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Small scratch(es)	Polish	No





Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Left Front	Damaged	Acceptable	Yes





Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes







Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Right	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Front	Damaged	Rim repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	Door-edge chipped	Acceptable	Yes





Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Rear	Damaged	Acceptable	Yes





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Scratch(es)	Spray	No







Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No