



### Peugeot 208: P652TR

Vinnnumber:	<b>VR3UHZKXZNT060185</b>	Versionname:	<b>e-208 50kWh 100kW Allure Pack automaat</b>
First Registrationdate:	<b>15/06/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>67951</b>	Power Kw:	<b>100</b>
Bodytype:		Body colour:	<b>Noir Perla Nera metaallak</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Type of rims (mounted):	<b>Steel</b>
Fueltype:	<b>Electric</b>	Parking lot:	<b>1158</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Steel</b>		
Maintenance needed:	<b>No</b>		

### Options

Number of keys total	<b>2</b>	Rear parking sensors
GPS		
Autom climate control		
Radio multimedia		

### Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 55 / 16 / 91 / H / Steel	5,0 mm	Michelin	Summer
	Right	195 / 55 / 16 / 91 / H / Steel	4,0 mm	Michelin	Summer
Rear	Left	195 / 55 / 16 / 91 / H / Steel	4,1 mm	Michelin	Summer
	Right	195 / 55 / 16 / 91 / H / Steel	4,0 mm	Michelin	Summer

### Assistance equipment

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>1</b>

### Door FL, Dent(s) and scratch(es), Repair and paint (complete)



### Door RL, Scratch(es), Repair and paint (complete)



### Wing FL, Scratch(es), Repair and paint (complete)



Bonnet, Chemical polution, Polish



Bumper F, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Outer door handle FR, Scratch(es), Repair and paint (complete)



Rear spoiler, Chemical polution, Polish



Bumper R, Scratch(es), Repair and paint (complete)



<b>Kenteken</b>	P652TR
<b>Merk Model</b>	Peugeot e-208 50kWh 100kW Allure Pack automaat
<b>Brandstofsoort</b>	Elektrisch
<b>Datum deel1</b>	15-06-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
26-05-26	66.877	APK
18-06-25	62.362	ABS pomp
28-04-25	53.003	Onderhoudsbeurt
28-04-25	53.003	Vervanging band
10-04-24	33.853	Onderhoudsbeurt
31-01-23	12.554	Onderhoudsbeurt