



Vehicle History Report

MERCEDES Maybach S 680 4MATIC

Vehicle reference:

W1K2239791A139901

Body type:
Sedan

Fuel type:
Petrol

Engine size:
5980 cm³

Drive:
AWD

Gearbox type:
Automatic

Number of doors:
4

Quick Check

Damage

This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.

 **Damage**

Import

Not a private import

 **No issues reported**

Located in Italy




Vehicle age

**3 years
4 months**

Damage Overview

04/2023 Damage reported



Affected area:

- Left

Severity scale:

Minor

Damage type/cause:


Not available

Reported on:


04/2023

Reported in:

Italy



05/2023 Damage reported



Affected area:

- Front
- Left
- Left front
- Rear

Severity scale:

Minor

Damage type/cause:


Not available

Reported on:

05/2023

Reported in:

Italy



Damage Glossary

Damage

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

Owners BETA



Owner(s) in Italy

Purchase year:	2022
Damage reported on:	05/2023 , 04/2023

History information

Date	Event
2022-11-10	Registered in Italy
04/2023	Damage reported in Italy
05/2023	Damage reported in Italy

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

Technical details	
Engine and performance	
Fuel type	Petrol
Other information	
Number of doors	4

CARFAX Glossary

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our [Terms and conditions.](#)