Ford Transit Closed Box Taillift 130pk 2021

WF0AXXTTRAMU00566 · lot Costs



VEHICLE DATA & SPECIFICATIONS

VIN	wf0axxttramu00566
First Registration	6/28/2021
Country of Origin	Netherlands
Mileage	269,615 km
Ford Transit Closed Box Taillift...	Lot: 61Veghel, NetherlandsFirst registration: June 28, 2021Mileage: 269,615 km130 hp
Front / Right	Back / Left
Place your bid	Auto-bid
Transport costs	
Vehicle location	
HP/PK	130 hp
Power type	Diesel
Emission norm	Euro 6
Engine Type	BKFB
Cilinder Amount	4
Distribution type	Belt
Engine displacement (cc)	1995
Airco option	airco
Mileage	269615 km
Number of seats	3
Type of cabin	Single
Type of Radio	DAB

VEHICLE DATA & SPECIFICATIONS - CONTINUED

Amount of Axles	2
Type of suspension axle 2	parabolic
Tyre condition Axle 1 Left (MM)	4 mm
Tyre condition Axle 1 Right (M...	4 mm
Tyre condition Axle 2 Left (MM)	7 mm
Tyre condition Axle 2 Right (M...	6 mm
Tyre size Axle 1	235/65 R16
Tyre Size Axle 2	235/65 R16
Undercarriage	Wheeled
Wheelbase	395 cm
Colour	white
Gross Vehicle Weight (GVW)	3500 kg
VIN / Serial Number/ Chassisn...	WF0AXXTTRAMU00566
Brand	Ford
Model	Transit
Product Group (Tax)	Closed Box
Axle capacity 1	1750 kg
Axle configuration	2002-10-04
Country of origin	NL
Type of drive	FWD
Type extended	Transit 130pk
Door opening height	229 cm
Door opening width	208 cm
Inner height	234 cm
Inner length	425 cm
Inner width	214 cm
Material floor	Wood
Superstructure brand	City Box
Superstructure build year	2021
Type of rear door	Tailgate
Empty weight	2687 kg
Registration Date	2021-06-28
Towing weight	1565 kg
M.O.T. approved till	2027-07-29
NAP	Logisch
Max load capacity	813 kg
Vehicle Height (cm)	327 cm
Vehicle Length (cm)	692 cm
Vehicle Width (cm)	222 cm
Tail lift capacity	750 kg
Plateau length	160 cm

VEHICLE DATA & SPECIFICATIONS - CONTINUED

Tail lift brand	Dhollandia
Tail lift build year	2021
Tail lift type	DHLM.10
Request Transaction Id	7571e65b-b519-4a4d-ba56-cfc6129dff82
Transmission	Manual
Amount of forward gears	6
Type Lights	Halogen
Truck ID	70342553
Lot	61
First registration	June 28, 2021
November 10, 2026 at 02	30 PM

Damage & Condition

All known damages are listed and shown in photos for full transparency.

1 damage reported | Worst: Minor




Multiple — Minor

Cosmetic Damage

.



Front / Right



Back / Left
















Porter
benzander
open

