



RENAULT Clio: GJ-075-JP

Vinnumber:	VF1RJA00569640377	Versionname:	CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)
First Registrationdate:	12/09/2022	Fiscalpower:	
Expertise Mileage:	122023	Power Kw:	
Bodytype:	Berline	Body colour:	White
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Hybrid	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Headlights Xenon/LED/Laser	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

	195/55/16/91 H			
Summer tyres:	Fr.L.	Hankook: 55%	Fr.R.	Hankook: 55%
	Re.L.	Hankook: 45%	Re.R.	Hankook: 50%
Tyre profile depth FL	4.5			
Tyre profile depth FR	4.5			
Tyre profile depth RL	5.1			
Tyre profile depth RR	5.0			
Tyre size FL	195/55 R 16 91 H			
Tyre size FR	195/55 R 16 91 H			
Tyre size RL	195/55 R 16 91 H			
Tyre size RR	195/55 R 16 91 H			
Tyre type FL	All seasons			
Tyre type FR	All Seasons			
Tyre type RL	All seasons			
Tyre type RR	All Seasons			
Tyre make FL	260			
Tyre make FR	260			
Tyre make RL	260			
Tyre make RR	260			

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Seat cover FR, Stain, Cleaning



Outside rear-view mirror housing L, Scratch(es), Polish



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Polish



Bumper F, Scratch(es), Paint



Wing RR, Dent(s), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Polish



Luggage compartment cover, Missing, Replace



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Paint



Bodywork, Not original part, Sticker removal small



Historique Maintenance

Immatriculation: **GJ-075-JP** Date de 1ère immatriculation: **12/09/2022**

Modèle: **Renault CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
17/12/2025	100.084	EURL JACQUET	DIAG
	0		RECYCLAGE
	0		DIVERS ELEC
11/12/2025	99.752	EURL JACQUET	REVISION ET CLIM
	0		RECYCLAGE
	0		BALAI ESSUIE GLACE AV
	0		LIQUIDE DE FREIN
04/09/2025	82.734	GARAGE TOISON D OR	POSE EQUILIBRAGE ROUES
	0		JANTE RPLT
01/09/2025	82.733	CONTITRADE FRANCE	GARDIENNAGE
	0		PERMUTATIONS PNEUS
17/04/2025	67.534	EURL JACQUET	RECYCLAGE
	0		DIVERS CARROSSERIE
14/04/2025	67.534	EURL JACQUET	RECYCLAGE
	0		REVISION ET CLIM ET AIR ET CARBURANT
26/11/2024	52.226	CONTITRADE FRANCE	REMPLACEMENT PNEUS HIVER
05/06/2024	36.065	DIJON AUTOMOBILE	REVISION
	0		GEOMETRIE CTRL
	0		RECYCLAGE
	0		PLAQUETTES AV RPLT
	0		PILE DE CLE RPLT
05/06/2024	36.065	DIJON AUTOMOBILE	REMPLACEMENT PNEUS ETE
	0		POSE EQUILIBRAGE ROUES
05/12/2023	27.437	DIJON AUTOMOBILE	BALAI ESSUIE GLACE AR
	0		BALAI ESSUIE GLACE AV