



Opel Corsa (UKL): 2BFD141

Vinnumber:	VXKUBYHTKM4314161	Versionname:	Corsa Edition 1.5 Turbo D 102pk/cv Start/Stop 5p
First Registrationdate:	29/10/2021	Fiscalpower:	
Expertise Mileage:	140190	Power Kw:	75
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Diesel		
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	195/55/16/87 H			
Summer tyres:	Fr.L.	Hankook: 4 mm	Fr.R.	Hankook: 4 mm
	Re.L.	Hankook: 5 mm	Re.R.	Hankook: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				195/55 R 16 87 H
Tyre size FR				195/55 R 16 87 H
Tyre size RL				195/55 R 16 87 H
Tyre size RR				195/55 R 16 87 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Seat cover FR, Stain, Cleaning



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)




Door FL, Dent(s), Paintless dent repair



Wing RR, Dent(s), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Kenteken	2BFD141
Merk Model	Opel Corsa Edition 1.5 Turbo D 102pk/cv Start/Stop 5p
Brandstofsoort	Diesel
Datum deel1	10/29/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
4/29/26	139,415	140000 km	Uitvoeren
4/29/26	139,415	oliezeef	Vervangen
10/9/25	119,943	halogeenlamp	Vervangen
9/19/25	117,240	120000 km	Uitvoeren
9/19/25	117,240	brandstof hoofdfilter	Vervangen
9/19/25	117,240	luchtfilter	Vervangen
9/19/25	117,240	luchtfilter interieur	Vervangen
9/19/25	117,240	oliezeef	Vervangen
9/19/25	117,240	remvloeistof	Vervangen
9/19/25	117,240	riem of multiriem	Vervangen
9/19/25	117,240	ruitenswisserrubber vooraan	Vervangen
11/8/24	92,120	remschijven en blokken vooraan	Vervangen
10/16/24	90,663	90000 km	Uitvoeren
10/16/24	90,663	luchtfilter interieur	Vervangen
10/16/24	90,663	oliezeef	Vervangen
10/16/23	60,729	60000 km	Uitvoeren
10/16/23	60,729	brandstof hoofdfilter	Vervangen
10/16/23	60,729	luchtfilter	Vervangen
10/16/23	60,729	luchtfilter interieur	Vervangen
10/16/23	60,729	oliezeef	Vervangen
10/16/23	60,729	remvloeistof	Vervangen
11/8/22	29,735	30000 km	Uitvoeren
11/8/22	29,735	oliezeef	Vervangen